# **Historic Libertyville**

Domestic - multiple dwelling

**BEGINNING STREET NUMBER** 114-116 **END STREET NUMBER** STREET # SUFFIX STREET NAME **Broadway Avenue** PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? LOCAL LANDMARK? **YEAR** Photo Id: BroadwayAve114-116(1) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING R-8 NUMBER OF STORIES **GROUND FLOOR USE** Residential Apartments **UPPER FLOOR USE** PROPERTY INDEX NUMBER Residential Apartments CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No ALTERNATE ADDRESS? NR LANDMARK? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION SECONDARY STRUCTURE Good INTEGRITY NR SECOND Historic alterations and additions **CURRENT USE** 

### **ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Queen Anne	Concrete-block
DETAILS	PORCH
-	Wrap around
OTHER YEAR	WINDOW MATERIA
1925 (c.)	Wood
DATE SOURCE	WINDOW MATERIA
Surveyor/Sanborns	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIG
-	1/1; 3/1
PLAN	SIGNIFICANCE
L	-
NO OF STORIES	HISTORIC FEATUR
2	Based on exterior fo
ROOF TYPE	appears to have ori
Hipped	altered around 192
ROOF MATERIAL	massing and the 1.

Asphalt - shingle

#### ΑL

#### AL 2

#### URATION

#### ES

eatures and Sanborn maps, the house iginally been a late 19th century Queen Anne verted to multi-family use and extensively 5. The steep hipped roof at the center of the 5-story east side bay with 1st story cutaway corners is original; an original square, canted bay at the southeast corner of the facade was obscured by a 2-story addition from 1925; the two-story west wing, wrap around porch, and double entries also date from 1925.

#### ALTERATIONS

More recent alterations include replacement siding; 1-story rear addition; replacement front doors; replacement front steps and railing

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: Broadway114116



Photo Id: Broadway114

### **HISTORIC INFORMATION**

-	
	ļ-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	-
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
DEDMIT /UICTO	DIC INFORMATION
PERMIT/HISTORIC INFORMATION	
OLD ADDRESS	DATE OF CONSTRUCTION
-	1890 (c.)
PERMIT MOVIN	NG INFORMATION
-	
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PERMIT INFORMATION	
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	
-	Sanborn Fire Insurance Company Maps, 1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
-	-
- DATE - BUILDING PERMIT DESCRIPTION - COST	- COA INFO - HISTORIC INFO - OTHER SOURCES Sanborn Fire Insurance Company Maps, 1924, 1933, 1948