Historic Libertyville

Domestic - single dwelling

| BEGINNING STREET NUMBER | 104 | |
|---------------------------------|--------------|----------------------------|
| END STREET NUMBER | - | |
| STREET # SUFFIX | - | |
| STREET NAME | First Street | |
| PIN | | |
| LOCAL | | |
| WITHIN LOCAL DISTRICT? | No | |
| LOCAL DIST CONTRIB/NON-CONTRIB? | С | |
| LOCAL LANDMARK? | No | |
| YEAR | - | |
| LOCAL LANDMARK ELIGIBLE? | No | Photo Id: FirstSt104(1) |
| CRITERIA | - | |
| | | |
| | <u>BU</u> | <u>ILDING DETAILS</u> |
| BUILDING NAME | | ZONING |
| - | | R-8 |
| GROUND FLOOR USE | | NUMBER OF STORIES |
| Residence | | 1.5 |
| UPPER FLOOR USE | | PROPERTY INDEX NUMBER |
| Residential | | 1121204007 |
| CURRENT OCCUPANT | | |
| - | | |
| | NAT | TIONAL REGISTER |
| | | |
| NR DISTRICT CONTRIB/NON-CONTRIB | | NR ELIGIBLE? |
| С | | No |
| WITHIN DISTRICT? | | CRITERIA |
| No | | - |
| NR LANDMARK? | | ALTERNATE ADDRESS? |
| No | | - |
| YEAR | | |
| - | | |
| | GENE | RAL INFORMATION |
| | | |
| CATEGORY | | HISTORIC USE |
| Building | | Domestic - single dwelling |
| CONDITION | | SECONDARY STRUCTURE |
| Good | | Detached garage |
| INTEGRITY | | NR SECOND |
| Historic alterations | | С |
| CURRENT USE | | |

ARCHITECTURAL DESCRIPTION

| ARCHITECTURAL CLASSIFICATION | FOUNDATION |
|------------------------------|---|
| Gable Front | Parged |
| DETAILS | PORCH |
| Craftsman | - |
| OTHER YEAR | WINDOW MATERIAL |
| 1950 (c) | Wood |
| DATE SOURCE | WINDOW MATERIAL 2 |
| Assessor, Sanborn Map (1948) | - |
| WALL MATERIAL (CURRENT) | WINDOW TYPE |
| Aluminum/vinyl | Double Hung |
| WALL MATERIAL 2 (CURRENT) | WINDOW CONFIGURATION |
| - | 1/1 |
| PLAN | SIGNIFICANCE |
| Rectangular | - |
| NO OF STORIES | HISTORIC FEATURES |
| 1.5 | Historic photograph of building shortly aft |
| ROOF TYPE | and Sanborn maps indicate that the hous altered some time after 1948. Front gable |
| Front Gable | massing are intact. |
| ROOF MATERIAL | ALTERATIONS |

Asphalt - shingle

fter it was constructed se was extensively le roof and rectangular

Historic alterations (c. 1950) include: removal of full front porch; 1-story entry bay, pent roof at 1st story facade; three-sided window bay on 1st story of south facade. Other alterations include one-story rear addition; replacement siding; fixed shutters

ADDITIONAL PHOTOGRAPHS



Photo Id: FirstSt104(4)



Photo Id: FirstStreet104

HISTORIC INFORMATION

| OLD ADDRESS (CITY DIR.YEAR | BUILDER |
|----------------------------------|--|
| - | - |
| BUILDING MOVED? | SURVEYOR |
| - | LR |
| MOVED FROM | SURVEYOR ORGANIZATION |
| - | Ramsey Historic Consultants |
| ORIGINAL OWNER | SURVEY DATE |
| McDonald, Edw. | May-June 2016 |
| ORIGINAL ARCHITECT | SURVEY AREA |
| - | Downtown Libertyville |
| ARCHITECT SOURCE | |
| - | |
| | |
| PERMII/F | <u> IISTORIC INFORMATION</u> |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| - | - |
| PERMIT | MOVING INFORMATION |
| | |
| MOVING PERMIT # | DATE MOVED |
| - | - |
| | |
| ORIGINAL | <u>L PERMIT INFORMATION</u> |
| | |
| BUILDING PERMIT # | OTHER PERMIT INFORMATION |
| - | - |
| DATE | COA INFO |
| - | - |
| BUILDING PERMIT DESCRIPTION | HISTORIC INFO |
| - | Historic photo of house at Illinois Digital Archives: |
| COST | http://www.idaillinois.org/cdm/singleitem/collection/cookmemo1 1/id/6524/rec/3 |
| - | OTHER SOURCES |
| ORIGINAL OWNER OCCUPIED? | Sanborn Maps (1933, 1948) |
| - | HISTORIC INFO COMPILER |
| EXTERIOR ALTERATION PERMITS | LR |
| JRF-11-0041 (5/4/11)replace roof | VOLUNTEER |
| | |