

Historic Libertyville

| | |
|--|-----------------|
| BEGINNING STREET NUMBER | 228 |
| END STREET NUMBER | - |
| STREET # SUFFIX | - |
| STREET NAME | Newberry Avenue |
| PIN | |
| LOCAL | |
| WITHIN LOCAL DISTRICT? | No |
| LOCAL DIST CONTRIB/NON-CONTRIB? | C |
| LOCAL LANDMARK? | No |
| YEAR | - |
| LOCAL LANDMARK ELIGIBLE? | Yes |
| CRITERIA | A |



Photo Id: NewberryAve228(3)

BUILDING DETAILS

| | | | |
|-------------------------|-------------|------------------------------|-------------------------|
| BUILDING NAME | - | ZONING | R-7 |
| GROUND FLOOR USE | Residential | NUMBER OF STORIES | 1.5 |
| UPPER FLOOR USE | Residential | PROPERTY INDEX NUMBER | 1116400001 - 1116403021 |
| CURRENT OCCUPANT | - | | |

NATIONAL REGISTER

| | | | |
|--|----|---------------------------|----|
| NR DISTRICT CONTRIB/NON-CONTRIB | C | NR ELIGIBLE? | No |
| WITHIN DISTRICT? | No | CRITERIA | - |
| NR LANDMARK? | No | ALTERNATE ADDRESS? | - |
| YEAR | - | | |

GENERAL INFORMATION

| | | | |
|--------------------|----------------------------|----------------------------|----------------------------|
| CATEGORY | Building | HISTORIC USE | Domestic - single dwelling |
| CONDITION | Good | SECONDARY STRUCTURE | Detached garage |
| INTEGRITY | Minor alterations | NR SECOND | NC |
| CURRENT USE | Domestic - single dwelling | | |

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Craftsman Bungalow

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Surveyor/Sanborn Maps

WALL MATERIAL (CURRENT)

Wood

WALL MATERIAL 2 (CURRENT)

Wood - shingles

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

Side Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Concrete-block

PORCH

Full Front

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

3/1

SIGNIFICANCE

Substantial Craftsman Bungalow with very high degree of architectural integrity.

HISTORIC FEATURES

Side gable roof with overhanging eaves; front dormer with triangular pediment; inset full front porch with square wood columns on solid knee walls; historic wood double hung windows; wood shingles on gable walls

ALTERATIONS

rear deck addition (1998)

ADDITIONAL PHOTOGRAPHS



Photo Id: NewberryAve228(2)



Photo Id: NewberryAve228(4)



Photo Id: Newberry228

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

98-580 (7/16/1998)--kitchen alterations and deck addition

OTHER PERMIT INFORMATION

79-3 (7/6/1979)--garage

COA INFO

-

HISTORIC INFO

Sanborn Maps--1924, 1933, 1948

OTHER SOURCES

-

HISTORIC INFO COMPILER

LR

VOLUNTEER

-