

# Historic Libertyville

BEGINNING STREET NUMBER	125
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	W. Park Avenue
PIN	
<b><u>LOCAL</u></b>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ParkAveW125(2)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	<b>ZONING</b>
-	C-2
<b>GROUND FLOOR USE</b>	<b>NUMBER OF STORIES</b>
Commercial/Office	2
<b>UPPER FLOOR USE</b>	<b>PROPERTY INDEX NUMBER</b>
Unknown	1121109004
<b>CURRENT OCCUPANT</b>	
Griswold Home Care	

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	<b>NR ELIGIBLE?</b>
C	No
<b>WITHIN DISTRICT?</b>	<b>CRITERIA</b>
No	-
<b>NR LANDMARK?</b>	<b>ALTERNATE ADDRESS?</b>
No	-
<b>YEAR</b>	
-	

## **GENERAL INFORMATION**

<b>CATEGORY</b>	<b>HISTORIC USE</b>
Building	Domestic - single dwelling
<b>CONDITION</b>	<b>SECONDARY STRUCTURE</b>
Good	-
<b>INTEGRITY</b>	<b>NR SECOND</b>
Moderate alterations	-
<b>CURRENT USE</b>	
Commerce/Trade - office	

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Queen Anne/Shingle

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Assessor

## **WALL MATERIAL (CURRENT)**

Aluminum/vinyl

## **WALL MATERIAL 2 (CURRENT)**

Wood - shingles

## **PLAN**

Rectangular

## **NO OF STORIES**

2.5

## **ROOF TYPE**

Side Gable

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Parged

## **PORCH**

Full Front

## **WINDOW MATERIAL**

Aluminum/vinyl

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

Double hung & casement

## **WINDOW CONFIGURATION**

1/1; 1-light

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

Side gable roof with cornice returns; three-sided east oriel bay window; inset front porch structure (altered)

## **ALTERATIONS**

Sanborn maps from 1924-1948 show house with full-front, open porch--porch partially enclosed at center, removed at west end, with open entry porch at east end; replacement windows in original openings on side elevations; inset porch in front dormer enclosed with casement windows; replacement siding

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: ParkAveW125(1)



Photo Id: Park125W



Photo Id: WParkAve125(2)

## **HISTORIC INFORMATION**

**OLD ADDRESS (CITY DIR.YEAR**

-

**BUILDING MOVED?**

-

**MOVED FROM**

-

**ORIGINAL OWNER**

-

**ORIGINAL ARCHITECT**

-

**ARCHITECT SOURCE**

-

**BUILDER**

-

**SURVEYOR**

LR

**SURVEYOR ORGANIZATION**

Ramsey Historic Consultants

**SURVEY DATE**

May-June 2016

**SURVEY AREA**

Downtown Libertyville

## **PERMIT/HISTORIC INFORMATION**

**OLD ADDRESS**

-

**DATE OF CONSTRUCTION**

-

## **PERMIT MOVING INFORMATION**

**MOVING PERMIT #**

-

**DATE MOVED**

-

## **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #**

-

**DATE**

-

**BUILDING PERMIT DESCRIPTION**

-

**COST**

-

**ORIGINAL OWNER OCCUPIED?**

-

**EXTERIOR ALTERATION PERMITS**

JCM-13-0028 (1/2/2014)--three replacement windows in apartment; 99-732 (7/22/1999)--addition; architectural drawing (no date)--alterations to rear facade (replacement siding, 2nd-story door and exterior staircase)

**OTHER PERMIT INFORMATION**

-

**COA INFO**

-

**HISTORIC INFO**

Sanborn Maps--1924 (Sheet 9); 1933 (Sheet 5); 1948 (Sheet 5)  
Mid-1970s photograph from IHSS

**OTHER SOURCES**

-

**HISTORIC INFO COMPILER**

LR

**VOLUNTEER**

-