

# Historic Libertyville

BEGINNING STREET NUMBER	213
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	W. Maple Avenue
PIN	
<b><u>LOCAL</u></b>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: MapleAveW213(1)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	<b>ZONING</b>
-	R-7
<b>GROUND FLOOR USE</b>	<b>NUMBER OF STORIES</b>
Residential	2
<b>UPPER FLOOR USE</b>	<b>PROPERTY INDEX NUMBER</b>
Residential	1116315014
<b>CURRENT OCCUPANT</b>	
-	

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	<b>NR ELIGIBLE?</b>
C	No
<b>WITHIN DISTRICT?</b>	<b>CRITERIA</b>
No	-
<b>NR LANDMARK?</b>	<b>ALTERNATE ADDRESS?</b>
No	-
<b>YEAR</b>	
-	

## **GENERAL INFORMATION**

<b>CATEGORY</b>	<b>HISTORIC USE</b>
Building	Domestic - single dwelling
<b>CONDITION</b>	<b>SECONDARY STRUCTURE</b>
Good	-
<b>INTEGRITY</b>	<b>NR SECOND</b>
Minor alterations and additions	-
<b>CURRENT USE</b>	
Domestic - single dwelling	

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Gable Front

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Assessor

## **WALL MATERIAL (CURRENT)**

Aluminum/vinyl

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

Rectangular

## **NO OF STORIES**

2.5

## **ROOF TYPE**

Front Gable

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Parged

## **PORCH**

Wrap around

## **WINDOW MATERIAL**

Wood

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

Double Hung

## **WINDOW CONFIGURATION**

1/1

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

Front gable roof and rectangular massing; 2-story east side gable bay; some historic windows (1st and 2nd stories of front facade

## **ALTERATIONS**

Replacement siding; some replacement windows in original openings on side elevation; new window under front gable; extensive alterations to porch (concrete base and steps, wrought iron railings); 1 story rear addition (1980); rear deck addition (1980)

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: MapleAveW213(2)



Photo Id: maple213

## **HISTORIC INFORMATION**

**OLD ADDRESS (CITY DIR.YEAR**

-

**BUILDING MOVED?**

-

**MOVED FROM**

-

**ORIGINAL OWNER**

-

**ORIGINAL ARCHITECT**

-

**ARCHITECT SOURCE**

-

**BUILDER**

-

**SURVEYOR**

LR

**SURVEYOR ORGANIZATION**

Ramsey Historic Consultants

**SURVEY DATE**

May-June 2016

**SURVEY AREA**

Downtown Libertyville

## **PERMIT/HISTORIC INFORMATION**

**OLD ADDRESS**

-

**DATE OF CONSTRUCTION**

-

## **PERMIT MOVING INFORMATION**

**MOVING PERMIT #**

-

**DATE MOVED**

-

## **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #**

-

**DATE**

-

**BUILDING PERMIT DESCRIPTION**

-

**COST**

-

**ORIGINAL OWNER OCCUPIED?**

-

**EXTERIOR ALTERATION PERMITS**

#2901 (7/19/1961)--repair front porch (new floor, ceiling, cornice boards, railing and columns), remove side door, install window; 79-185 (8/15/1980)--addition; JB-05-0029 (5/2/2006)-shed

**OTHER PERMIT INFORMATION**

-

**COA INFO**

-

**HISTORIC INFO**

-

**OTHER SOURCES**

Sanborn Maps--1924, 1933, 1948

**HISTORIC INFO COMPILER**

LR

**VOLUNTEER**

-