

# Historic Libertyville

<b>BEGINNING STREET NUMBER</b>	307
<b>END STREET NUMBER</b>	-
<b>STREET # SUFFIX</b>	-
<b>STREET NAME</b>	Brainerd Avenue
<b>PIN</b>	
<b><u>LOCAL</u></b>	
<b>WITHIN LOCAL DISTRICT?</b>	No
<b>LOCAL DIST CONTRIB/NON-CONTRIB?</b>	C
<b>LOCAL LANDMARK?</b>	No
<b>YEAR</b>	-
<b>LOCAL LANDMARK ELIGIBLE?</b>	Yes
<b>CRITERIA</b>	A



Photo Id: BrainerdAve307(1)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	-	<b>ZONING</b>	R-6
<b>GROUND FLOOR USE</b>	Residence	<b>NUMBER OF STORIES</b>	2
<b>UPPER FLOOR USE</b>	Residential	<b>PROPERTY INDEX NUMBER</b>	1116310042
<b>CURRENT OCCUPANT</b>	-		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	C	<b>NR ELIGIBLE?</b>	No
<b>WITHIN DISTRICT?</b>	No	<b>CRITERIA</b>	-
<b>NR LANDMARK?</b>	No	<b>ALTERNATE ADDRESS?</b>	-
<b>YEAR</b>	-		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	Building	<b>HISTORIC USE</b>	Domestic - single dwelling
<b>CONDITION</b>	Good	<b>SECONDARY STRUCTURE</b>	Detached garage
<b>INTEGRITY</b>	Moved; minor alterations	<b>NR SECOND</b>	NC
<b>CURRENT USE</b>	Domestic - single dwelling		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Italianate

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Assessor

## **WALL MATERIAL (CURRENT)**

Wood

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

Rectangular

## **NO OF STORIES**

2

## **ROOF TYPE**

Hipped

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Concrete-block

## **PORCH**

-

## **WINDOW MATERIAL**

Wood

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

Double Hung

## **WINDOW CONFIGURATION**

1/1

## **SIGNIFICANCE**

Handsome 19th-century Italianate residence with characteristic bracketed cornice and ornamental window surrounds. House was moved to current location in 1957.

## **HISTORIC FEATURES**

Low-pitched hipped roof; paneled wood frieze with wood brackets; symmetrical facade with center entry; ornamental wood window surrounds

## **ALTERATIONS**

House moved in 1957 (concrete block foundation); replacement front stoop; replacement windows in original openings (historically appropriate type and configuration)

**ADDITIONAL PHOTOGRAPHS**



Photo Id: BrainerdAve307(2)



Photo Id: Brainerd307



Photo Id: Brainerd307

## HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

-

BUILDING MOVED?

Yes

MOVED FROM

Unknown

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

## PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

## PERMIT MOVING INFORMATION

MOVING PERMIT #

1787

DATE MOVED

5/13/1957

## ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

-

OTHER PERMIT INFORMATION

#97-891 (11/13/1997)--detached garage

COA INFO

-

HISTORIC INFO

-

OTHER SOURCES

-

HISTORIC INFO COMPILER

LR

VOLUNTEER

-