Historic Libertyville

Domestic - single dwelling

| BEGINNING STREET NUMBER | 311 | |
|------------------------------------|--------------------|-----------------------------|
| END STREET NUMBER | - | |
| STREET # SUFFIX | - | |
| STREET NAME | Brainerd Avenue | |
| PIN | | |
| LOCAL | | |
| WITHIN LOCAL DISTRICT? | No | |
| LOCAL DIST CONTRIB/NON-CONTRIB? | С | |
| LOCAL LANDMARK? | No | |
| YEAR | - | |
| LOCAL LANDMARK ELIGIBLE? | No | Photo Id: BrainerdAve311(1) |
| CRITERIA | - | |
| | BUTI DIN | IG DETAILS |
| | DOILDIN | TO DETAILS |
| BUILDING NAME | | ZONING |
| - | | R-6 |
| GROUND FLOOR USE | | NUMBER OF STORIES |
| Residence | | 2 |
| UPPER FLOOR USE | | PROPERTY INDEX NUMBER |
| Residential | | 1116300130 |
| CURRENT OCCUPANT | | |
| - | | |
| | NATIONA | AL REGISTER |
| | | |
| NR DISTRICT CONTRIB/NON-CONTRIB | | NR ELIGIBLE? |
| С | | No |
| WITHIN DISTRICT? | | CRITERIA |
| No | | - |
| NR LANDMARK? | | ALTERNATE ADDRESS? |
| No | | - |
| YEAR | | |
| - | | |
| | GENERAL T | <u>NFORMATION</u> |
| | <u>OLIVEIUVE 1</u> | |
| CATEGORY | | HISTORIC USE |
| Building | | Domestic - single dwelling |
| CONDITION | | SECONDARY STRUCTURE |
| Good | | Detached garage |
| INTEGRITY | | NR SECOND |
| Moderate alterations and additions | | NC |
| CUDDENT LICE | | |

ARCHITECTURAL DESCRIPTION

| ARCHITECTURAL CLASSIFICATION | FOUNDATION |
|------------------------------|-------------------------------------------------------------------------------------------------------------------------|
| Queen Anne | Brick |
| DETAILS | PORCH |
| - | - |
| OTHER YEAR | WINDOW MATERIAL |
| - | Wood |
| DATE SOURCE | WINDOW MATERIAL 2 |
| Surveyor | - |
| WALL MATERIAL (CURRENT) | WINDOW TYPE |
| Wood | Combination |
| WALL MATERIAL 2 (CURRENT) | WINDOW CONFIGURATION |
| Wood - shingles | Combination |
| PLAN | SIGNIFICANCE |
| Irregular | - |
| NO OF STORIES | HISTORIC FEATURES |
| 2.5 | Front gable roof with pent enclosure; 2-story side gable bay; |
| ROOF TYPE | first-story oriel bay on southwest facade |
| Multi-gable | ALTERATIONS |
| ROOF MATERIAL | Front entry porch (enclosed in 1953); replacement windows in original openings; 2-story rear addition (1998); 1.5-story |

southwest side addition (2003)

Asphalt - shingle

ADDITIONAL PHOTOGRAPHS



Photo Id: BrainerdAve311(3)



Photo Id: Brainerd311(3)



Photo Id: Brainerd311

HISTORIC INFORMATION

| OLD ADDRESS (CITY DIR.YEAR | BUILDER |
|--------------------------------------------------------------------------------------------------------------|-----------------------------|
| - | - |
| BUILDING MOVED? | SURVEYOR |
| - | LR |
| MOVED FROM | SURVEYOR ORGANIZATION |
| - | Ramsey Historic Consultants |
| ORIGINAL OWNER | SURVEY DATE |
| - | May-June 2016 |
| ORIGINAL ARCHITECT | SURVEY AREA |
| - | Downtown Libertyville |
| ARCHITECT SOURCE | |
| - | |
| | <u>.</u> |
| PERMIT/HIST | ORIC INFORMATION |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| - | - |
| DEDIATE MOVE | |
| PERMIT MOV. | ING INFORMATION |
| MOVING PERMIT # | DATE MOVED |
| - | - |
| ODICINAL DE | DATE INCORMATION |
| ORIGINAL PER | RMIT INFORMATION |
| BUILDING PERMIT # | OTHER PERMIT INFORMATION |
| - | #1250 (8/22/1955)garage |
| DATE | COA INFO |
| - | - |
| BUILDING PERMIT DESCRIPTION | HISTORIC INFO |
| - | - |
| COST | OTHER SOURCES |
| - | - |
| ORIGINAL OWNER OCCUPIED? | HISTORIC INFO COMPILER |
| - | LR |
| EXTERIOR ALTERATION PERMITS | VOLUNTEER |
| #98-615 (6/8/1998)2-story rear addition; JRA-03-0039 (7/2/2003)1.5-story southwest addition; #412 (8/6/1952) | - |