Historic Libertyville

Domestic - single dwelling

BEGINNING STREET NUMBER 154 **END STREET NUMBER** STREET # SUFFIX **STREET NAME** Broadway PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? LOCAL LANDMARK? **YEAR** Photo Id: BroadwayAve154(1) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING R-8 GROUND FLOOR USE NUMBER OF STORIES Residence UPPER FLOOR USE PROPERTY INDEX NUMBER N/A 1116415021 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No NR LANDMARK? ALTERNATE ADDRESS? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION SECONDARY STRUCTURE Good INTEGRITY NR SECOND Minor alterations and additions **CURRENT USE**

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front Cottage	Not visible
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Wood	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
Irregular	-
NO OF STORIES	HISTORIC FEATURES
1.5	Front gable roof and rectangular massing of original structure;
ROOF TYPE	front porch structure; west and rear (north) additions appear to be early (pre-1925)
Multi-gable	ALTERATIONS
ROOF MATERIAL	Some replacement windows in original openings.

Asphalt - shingle

ADDITIONAL PHOTOGRAPHS



Photo Id: BroadwayAve154(2)



Photo Id: Broadway153

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
PERMIT/HISTOR	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
	IG INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PERM	<u>IIT INFORMATION</u>
DUVI DANG DEDAYT #	OTHER REPORT THEORY
BUILDING PERMIT #	OTHER PERMIT INFORMATION
	[-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Fire Insurance Company Maps, 1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
00-66 (2/21/2000)rebuilt front porch, leaving roof in place; 2573 (2/2/1960)interior work, 2nd floor; 2 rooms and kitchen, 2 dormers, exterior stairway	-