Historic Libertyville

Domestic - single dwelling

BEGINNING STREET NUMBER	112	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Douglas Avenue	
PIN		
LOCAL		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	A MANAGE AND A STANKER OF THE STANKE
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: DouglasAve112(1)
CRITERIA	-	
	<u>BUILD</u>	ING DETAILS
DUTI DANG NAME		TOWNS
BUILDING NAME		ZONING
GROUND FLOOR USE		R-8 NUMBER OF STORIES
		2
Residence UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential CURRENT OCCUPANT		1121105002
_		
_		
	<u>NATION</u>	NAL REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
C MITHIN DISTRICTS		No
WITHIN DISTRICT?		CRITERIA
No NR LANDMARK?		ALTERNATE ADDRESS?
No No		-
YEAR		
-		
	<u>GENERAL</u>	<u>INFORMATION</u>
CATEGORY		HISTORIC USE
Building		Domestic - single dwelling
CONDITION		SECONDARY STRUCTURE
Good		Detached garage
INTEGRITY		NR SECOND
Moderate alterations		NC NC

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Side Gable	Brick
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Wood	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Wood - shingles	-
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
1.5	Front gable roof; shed roof north and south dormers with gable ends; 4/1 historic wood windows on first story; west side sun porch with gable roof
ROOF TYPE	
Side Gable	ALTERATIONS
ROOF MATERIAL	
Asphalt - shingle	South side porch addition (1954); alterations to entry, replacement windows in original openings on 2nd story

ADDITIONAL PHOTOGRAPHS





Photo Id: douglas112(2)



Photo Id: douglas112

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
PERMIT/HISTOR	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
_	-
<u>PERMIT MOVIN</u>	<u>IG INFORMATION</u>
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PERM	<u>IIT INFORMATION</u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
JRR-15-0151 (12/14/2015)remodel kitchen, 1/2 bath, basement; 976 (10/9/1954)moving garage on lot; 884 (6/23/1954)add screened porch on south side facing Park Avenue; 700 (8/28/1953)repair and remodel entryway; repair and replace sidewalk and concrete slab	-