

Historic Libertyville

| | |
|---------------------------------|----------------|
| BEGINNING STREET NUMBER | 120 |
| END STREET NUMBER | - |
| STREET # SUFFIX | - |
| STREET NAME | Douglas Avenue |
| PIN | |
| <u>LOCAL</u> | |
| WITHIN LOCAL DISTRICT? | No |
| LOCAL DIST CONTRIB/NON-CONTRIB? | C |
| LOCAL LANDMARK? | No |
| YEAR | - |
| LOCAL LANDMARK ELIGIBLE? | No |
| CRITERIA | - |



Photo Id: DouglasAve120(1)

BUILDING DETAILS

| | |
|-------------------------|------------------------------|
| BUILDING NAME | ZONING |
| - | R-8 |
| GROUND FLOOR USE | NUMBER OF STORIES |
| Residence | 2 |
| UPPER FLOOR USE | PROPERTY INDEX NUMBER |
| Residential | 1121105001 |
| CURRENT OCCUPANT | |
| - | |

NATIONAL REGISTER

| | |
|--|---------------------------|
| NR DISTRICT CONTRIB/NON-CONTRIB | NR ELIGIBLE? |
| C | No |
| WITHIN DISTRICT? | CRITERIA |
| No | - |
| NR LANDMARK? | ALTERNATE ADDRESS? |
| No | - |
| YEAR | |
| - | |

GENERAL INFORMATION

| | |
|---------------------------------|----------------------------|
| CATEGORY | HISTORIC USE |
| Building | Domestic - single dwelling |
| CONDITION | SECONDARY STRUCTURE |
| Good | Detached garage |
| INTEGRITY | NR SECOND |
| Minor alterations and additions | C |
| CURRENT USE | |
| Domestic - single dwelling | |

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Tudor Revival

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Brick

WALL MATERIAL 2 (CURRENT)

Wood

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Not visible

PORCH

-

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

6/1; 4/1

SIGNIFICANCE

-

HISTORIC FEATURES

Broad, asymmetrical front gable roof that extends south to include a south side sun porch; prominent brick end chimney centered; nested 1-story front gable entry bay; round-arch front entry; historic wood windows

ALTERATIONS

South side shed-roof dormer addition; replacement front door; rear deck addition; glass block window on front facade at 2nd story

ADDITIONAL PHOTOGRAPHS



Photo Id: DouglasAve120(3)



Photo Id: douglas120

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

JD-01-0008 (7/25/2001)--deck

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

-

OTHER SOURCES

Sanborn Maps--1933, 1948

HISTORIC INFO COMPILER

LR

VOLUNTEER

-