

Historic Libertyville

BEGINNING STREET NUMBER	<input type="text" value="104"/>
END STREET NUMBER	<input type="text" value="-"/>
STREET # SUFFIX	<input type="text" value="-"/>
STREET NAME	<input type="text" value="First Street"/>
PIN	<input type="text" value=""/>
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	<input type="text" value="No"/>
LOCAL DIST CONTRIB/NON-CONTRIB?	<input type="text" value="C"/>
LOCAL LANDMARK?	<input type="text" value="No"/>
YEAR	<input type="text" value="-"/>
LOCAL LANDMARK ELIGIBLE?	<input type="text" value="No"/>
CRITERIA	<input type="text" value="-"/>



Photo Id: FirstSt104(1)

BUILDING DETAILS

BUILDING NAME	<input type="text" value="-"/>	ZONING	<input type="text" value="R-8"/>
GROUND FLOOR USE	<input type="text" value="Residence"/>	NUMBER OF STORIES	<input type="text" value="1.5"/>
UPPER FLOOR USE	<input type="text" value="Residential"/>	PROPERTY INDEX NUMBER	<input type="text" value="1121204007"/>
CURRENT OCCUPANT	<input type="text" value="-"/>		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	<input type="text" value="C"/>	NR ELIGIBLE?	<input type="text" value="No"/>
WITHIN DISTRICT?	<input type="text" value="No"/>	CRITERIA	<input type="text" value="-"/>
NR LANDMARK?	<input type="text" value="No"/>	ALTERNATE ADDRESS?	<input type="text" value="-"/>
YEAR	<input type="text" value="-"/>		

GENERAL INFORMATION

CATEGORY	<input type="text" value="Building"/>	HISTORIC USE	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="Good"/>	SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>
INTEGRITY	<input type="text" value="Historic alterations"/>	NR SECOND	<input type="text" value="C"/>
CURRENT USE	<input type="text" value="Domestic - single dwelling"/>		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Gable Front

DETAILS

Craftsman

OTHER YEAR

1950 (c)

DATE SOURCE

Assessor, Sanborn Map (1948)

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Parged

PORCH

-

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

1/1

SIGNIFICANCE

-

HISTORIC FEATURES

Historic photograph of building shortly after it was constructed and Sanborn maps indicate that the house was extensively altered some time after 1948. Front gable roof and rectangular massing are intact.

ALTERATIONS

Historic alterations (c. 1950) include: removal of full front porch; 1-story entry bay, pent roof at 1st story facade; three-sided window bay on 1st story of south facade. Other alterations include one-story rear addition; replacement siding; fixed shutters

ADDITIONAL PHOTOGRAPHS



Photo Id: FirstSt104(4)



Photo Id: FirstStreet104

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

McDonald, Edw.

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

JRF-11-0041 (5/4/11)--replace roof

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

Historic photo of house at Illinois Digital Archives:
<http://www.idaillinois.org/cdm/singleitem/collection/cookmemo11/id/6524/rec/3>

OTHER SOURCES

Sanborn Maps (1933, 1948)

HISTORIC INFO COMPILER

LR

VOLUNTEER

-