

Historic Libertyville

BEGINNING STREET NUMBER	104
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt104(1)

BUILDING DETAILS

BUILDING NAME	ZONING
-	R-8
GROUND FLOOR USE	NUMBER OF STORIES
Residence	1.5
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential	1121204007
CURRENT OCCUPANT	
-	

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
C	No
WITHIN DISTRICT?	CRITERIA
No	-
NR LANDMARK?	ALTERNATE ADDRESS?
No	-
YEAR	
-	

GENERAL INFORMATION

CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	Detached garage
INTEGRITY	NR SECOND
Historic alterations	C
CURRENT USE	
Domestic - single dwelling	

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Gable Front

DETAILS

Craftsman

OTHER YEAR

1950 (c)

DATE SOURCE

Assessor, Sanborn Map (1948)

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Parged

PORCH

-

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

1/1

SIGNIFICANCE

-

HISTORIC FEATURES

Historic photograph of building shortly after it was constructed and Sanborn maps indicate that the house was extensively altered some time after 1948. Front gable roof and rectangular massing are intact.

ALTERATIONS

Historic alterations (c. 1950) include: removal of full front porch; 1-story entry bay, pent roof at 1st story facade; three-sided window bay on 1st story of south facade. Other alterations include one-story rear addition; replacement siding; fixed shutters

ADDITIONAL PHOTOGRAPHS



Photo Id: FirstSt104(4)



Photo Id: FirstStreet104

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

McDonald, Edw.

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

JRF-11-0041 (5/4/11)--replace roof

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

Historic photo of house at Illinois Digital Archives:
<http://www.idaillinois.org/cdm/singleitem/collection/cookmemo11/id/6524/rec/3>

OTHER SOURCES

Sanborn Maps (1933, 1948)

HISTORIC INFO COMPILER

LR

VOLUNTEER

-