

Historic Libertyville

BEGINNING STREET NUMBER	<input type="text" value="113"/>
END STREET NUMBER	<input type="text" value="-"/>
STREET # SUFFIX	<input type="text" value="-"/>
STREET NAME	<input type="text" value="First Street"/>
PIN	<input type="text"/>
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	<input type="text" value="No"/>
LOCAL DIST CONTRIB/NON-CONTRIB?	<input type="text" value="NC"/>
LOCAL LANDMARK?	<input type="text" value="No"/>
YEAR	<input type="text" value="-"/>
LOCAL LANDMARK ELIGIBLE?	<input type="text" value="No"/>
CRITERIA	<input type="text" value="-"/>



Photo Id: FirstSt113(2)

BUILDING DETAILS

BUILDING NAME	<input type="text" value="-"/>	ZONING	<input type="text" value="R-7"/>
GROUND FLOOR USE	<input type="text" value="Residential"/>	NUMBER OF STORIES	<input type="text" value="2"/>
UPPER FLOOR USE	<input type="text" value="Residential"/>	PROPERTY INDEX NUMBER	<input type="text" value="1121203012"/>
CURRENT OCCUPANT	<input type="text" value="-"/>		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	<input type="text" value="NC"/>	NR ELIGIBLE?	<input type="text" value="No"/>
WITHIN DISTRICT?	<input type="text" value="No"/>	CRITERIA	<input type="text" value="-"/>
NR LANDMARK?	<input type="text" value="No"/>	ALTERNATE ADDRESS?	<input type="text" value="-"/>
YEAR	<input type="text" value="-"/>		

GENERAL INFORMATION

CATEGORY	<input type="text" value="Building"/>	HISTORIC USE	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="Good"/>	SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>
INTEGRITY	<input type="text" value="Major alterations and additions"/>	NR SECOND	<input type="text" value="C"/>
CURRENT USE	<input type="text" value="Domestic - single dwelling"/>		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Gable Front

DETAILS

Craftsman

OTHER YEAR

1920 (c); 1997

DATE SOURCE

Assessor/Surveyor/permit

WALL MATERIAL (CURRENT)

Wood - shingles

WALL MATERIAL 2 (CURRENT)

Wood

PLAN

Rectangular

NO OF STORIES

2

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Not visible

PORCH

Front entry

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Combination

WINDOW CONFIGURATION

Combination

SIGNIFICANCE

-

HISTORIC FEATURES

Front gable roof; hipped roof full-front porch structure (partially enclosed c. 1920); historic (but not original) 3/1 double hung windows on front facade

ALTERATIONS

Large 2-story rear addition that is taller than original house (1997); wood shingles on front facade (1951); front porch partially enclosed c. 1920; entry porch steps and railing are more recent

ADDITIONAL PHOTOGRAPHS



Photo Id: FirstSt113(4)



Photo Id: First113

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

Whitney, Lew

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

97-524 (7/11/1997)--rear addition (\$50,000); No Permit #
(11/2/1951)--reside house with John manvills Shingles

OTHER PERMIT INFORMATION

00-974 (2001)--addition to garage

COA INFO

-

HISTORIC INFO

Historic image of photograph on Illinois Digital Archives (in collection of Libertyville Mundelein Historical Society and Cook Memorial Public Library:
<http://www.idaillinois.org/cdm/singleitem/collection/cookmemo11/id/6501/rec/5> Back of photograph reads "House of Lew Whitney." According to Illinois Digital Archives, Whitney was a tinner.

OTHER SOURCES

Sanborn maps, 1933, 1948

HISTORIC INFO COMPILER

LR

VOLUNTEER

-