

# Historic Libertyville

<b>BEGINNING STREET NUMBER</b>	<input type="text" value="125"/>
<b>END STREET NUMBER</b>	<input type="text" value="-"/>
<b>STREET # SUFFIX</b>	<input type="text" value="-"/>
<b>STREET NAME</b>	<input type="text" value="First Street"/>
<b>PIN</b>	<input type="text"/>
<b><u>LOCAL</u></b>	
<b>WITHIN LOCAL DISTRICT?</b>	<input type="text" value="No"/>
<b>LOCAL DIST CONTRIB/NON-CONTRIB?</b>	<input type="text" value="C"/>
<b>LOCAL LANDMARK?</b>	<input type="text" value="No"/>
<b>YEAR</b>	<input type="text" value="-"/>
<b>LOCAL LANDMARK ELIGIBLE?</b>	<input type="text" value="No"/>
<b>CRITERIA</b>	<input type="text" value="-"/>



Photo Id: FirstSt125(2)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	<input type="text" value="-"/>	<b>ZONING</b>	<input type="text" value="R-6"/>
<b>GROUND FLOOR USE</b>	<input type="text" value="Residential"/>	<b>NUMBER OF STORIES</b>	<input type="text" value="2"/>
<b>UPPER FLOOR USE</b>	<input type="text" value="Residential"/>	<b>PROPERTY INDEX NUMBER</b>	<input type="text" value="1121203009"/>
<b>CURRENT OCCUPANT</b>	<input type="text" value="-"/>		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	<input type="text" value="C"/>	<b>NR ELIGIBLE?</b>	<input type="text" value="No"/>
<b>WITHIN DISTRICT?</b>	<input type="text" value="No"/>	<b>CRITERIA</b>	<input type="text" value="-"/>
<b>NR LANDMARK?</b>	<input type="text" value="No"/>	<b>ALTERNATE ADDRESS?</b>	<input type="text" value="-"/>
<b>YEAR</b>	<input type="text" value="-"/>		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	<input type="text" value="Building"/>	<b>HISTORIC USE</b>	<input type="text" value="Domestic - single dwelling"/>
<b>CONDITION</b>	<input type="text" value="Good"/>	<b>SECONDARY STRUCTURE</b>	<input type="text" value="Detached garage"/>
<b>INTEGRITY</b>	<input type="text" value="Moderate alterations"/>	<b>NR SECOND</b>	<input type="text" value="NC"/>
<b>CURRENT USE</b>	<input type="text" value="Domestic - single dwelling"/>		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Queen Anne

## **DETAILS**

-

## **OTHER YEAR**

1925 (c)

## **DATE SOURCE**

Assessor/Sanborn maps

## **WALL MATERIAL (CURRENT)**

Hardie board

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

Irregular

## **NO OF STORIES**

1.5

## **ROOF TYPE**

Hipped

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Brick

## **PORCH**

Corner entry

## **WINDOW MATERIAL**

Aluminum/vinyl

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

Double hung & casement

## **WINDOW CONFIGURATION**

6/6; 10-light

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

Steeply pitched hipped main roof; rectangular massing

## **ALTERATIONS**

Sanborn maps indicate that a polygonal front bay just north of the corner entry porch on the front facade was leveled off some time between 1924 and 1933; replacement front porch (2004); replacement siding; front gable through-the-wall dormer with round-arch window; replacement windows in original openings

**ADDITIONAL PHOTOGRAPHS**



Photo Id: FirstSt125(4)



Photo Id: First125

## **HISTORIC INFORMATION**

**OLD ADDRESS (CITY DIR.YEAR)**

**BUILDING MOVED?**

**MOVED FROM**

**ORIGINAL OWNER**

**ORIGINAL ARCHITECT**

**ARCHITECT SOURCE**

**BUILDER**

**SURVEYOR**

**SURVEYOR ORGANIZATION**

**SURVEY DATE**

**SURVEY AREA**

## **PERMIT/HISTORIC INFORMATION**

**OLD ADDRESS**

**DATE OF CONSTRUCTION**

## **PERMIT MOVING INFORMATION**

**MOVING PERMIT #**

**DATE MOVED**

## **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #**

**DATE**

**BUILDING PERMIT DESCRIPTION**

**COST**

**ORIGINAL OWNER OCCUPIED?**

**EXTERIOR ALTERATION PERMITS**

**OTHER PERMIT INFORMATION**

**COA INFO**

**HISTORIC INFO**

**OTHER SOURCES**

**HISTORIC INFO COMPILER**

**VOLUNTEER**