

# Historic Libertyville

<b>BEGINNING STREET NUMBER</b>	<input type="text" value="130"/>
<b>END STREET NUMBER</b>	<input type="text" value="-"/>
<b>STREET # SUFFIX</b>	<input type="text" value="-"/>
<b>STREET NAME</b>	<input type="text" value="First Street"/>
<b>PIN</b>	<input type="text"/>
<b><u>LOCAL</u></b>	
<b>WITHIN LOCAL DISTRICT?</b>	<input type="text" value="No"/>
<b>LOCAL DIST CONTRIB/NON-CONTRIB?</b>	<input type="text" value="C"/>
<b>LOCAL LANDMARK?</b>	<input type="text" value="No"/>
<b>YEAR</b>	<input type="text" value="-"/>
<b>LOCAL LANDMARK ELIGIBLE?</b>	<input type="text" value="No"/>
<b>CRITERIA</b>	<input type="text" value="-"/>



Photo Id: FirstSt130(2)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	<input type="text" value="-"/>	<b>ZONING</b>	<input type="text" value="R-6"/>
<b>GROUND FLOOR USE</b>	<input type="text" value="Residential"/>	<b>NUMBER OF STORIES</b>	<input type="text" value="2"/>
<b>UPPER FLOOR USE</b>	<input type="text" value="Residential"/>	<b>PROPERTY INDEX NUMBER</b>	<input type="text" value="1121204001"/>
<b>CURRENT OCCUPANT</b>	<input type="text" value="-"/>		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	<input type="text" value="C"/>	<b>NR ELIGIBLE?</b>	<input type="text" value="No"/>
<b>WITHIN DISTRICT?</b>	<input type="text" value="No"/>	<b>CRITERIA</b>	<input type="text" value="-"/>
<b>NR LANDMARK?</b>	<input type="text" value="No"/>	<b>ALTERNATE ADDRESS?</b>	<input type="text" value="-"/>
<b>YEAR</b>	<input type="text" value="-"/>		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	<input type="text" value="Building"/>	<b>HISTORIC USE</b>	<input type="text" value="Domestic - single dwelling"/>
<b>CONDITION</b>	<input type="text" value="Good"/>	<b>SECONDARY STRUCTURE</b>	<input type="text" value="Detached garage"/>
<b>INTEGRITY</b>	<input type="text" value="Minor alterations"/>	<b>NR SECOND</b>	<input type="text" value="C"/>
<b>CURRENT USE</b>	<input type="text" value="Domestic - single dwelling"/>		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Gable Front

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Assessor/Surveyor

## **WALL MATERIAL (CURRENT)**

Wood

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

Rectangular

## **NO OF STORIES**

2.5

## **ROOF TYPE**

Front Gable

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Brick

## **PORCH**

Full Front

## **WINDOW MATERIAL**

Wood

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

Double hung & casement

## **WINDOW CONFIGURATION**

1/1; 3/1

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

Front gable roof; rectangular massing; north side gable; historic 1/1 and 3/1 wood windows; hipped-roof full-front porch structure (enclosed)

## **ALTERATIONS**

Front porch enclosed (c. 1920); chimney added to north elevation; curving bay window on front wall of porch (not historic); rear deck addition

**ADDITIONAL PHOTOGRAPHS**



Photo Id: FirstSt130(4)



Photo Id: First130

## HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

Skinner, William

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

## PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

## PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

## ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

79-41 (1979)--Pre-fab fireplace; JF-14-0095 (2014)--patio

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

Historic photograph of house on Illinois Digital Archive--  
<http://www.idaillinois.org/cdm/singleitem/collection/cookmemo11/id/6506/rec/9>

OTHER SOURCES

Sanborn maps, 1924, 1933, 1948

HISTORIC INFO COMPILER

LR

VOLUNTEER

-