

Historic Libertyville

BEGINNING STREET NUMBER	203
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt203(1)

BUILDING DETAILS

BUILDING NAME	ZONING
-	R-6
GROUND FLOOR USE	NUMBER OF STORIES
Residential	2
UPPER FLOOR USE	PROPERTY INDEX NUMBER
Residential	1116422018
CURRENT OCCUPANT	
-	

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
C	No
WITHIN DISTRICT?	CRITERIA
No	-
NR LANDMARK?	ALTERNATE ADDRESS?
No	-
YEAR	
-	

GENERAL INFORMATION

CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	Detached garage
INTEGRITY	NR SECOND
Minor alterations	NC
CURRENT USE	
Domestic - single dwelling	

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Bungalow

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Surveyor

WALL MATERIAL (CURRENT)

Stucco

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

Side Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Parged

PORCH

Full Front

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

-

SIGNIFICANCE

-

HISTORIC FEATURES

Broad side gable roof with overhanging eaves; large gable-roof front dormer; inset full-front porch with square stucco piers set on stucco knee wall (enclosed); historic 6/1 wood windows; south side square oriel window bay

ALTERATIONS

Front porch enclosed (post-1948); wood and concrete front stoop is replacement; skylight

ADDITIONAL PHOTOGRAPHS



Photo Id: FirstSt203(2)



Photo Id: FirstStreet203

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

95-323 (1995)--repair fire damage (\$16,600.00)

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

-

OTHER SOURCES

Sanborn Maps (1924, 1933, 1948)

HISTORIC INFO COMPILER

LR

VOLUNTEER

-