Historic Libertyville

Major alterations

Domestic - single dwelling

CURRENT USE

BEGINNING STREET NUMBER 218 **END STREET NUMBER** STREET # SUFFIX **STREET NAME** First Street PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? NC LOCAL LANDMARK? No **YEAR** Photo Id: FirstSt218(1) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING R-6 GROUND FLOOR USE NUMBER OF STORIES Residential UPPER FLOOR USE PROPERTY INDEX NUMBER Residential 1116423009 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No NR LANDMARK? ALTERNATE ADDRESS? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION SECONDARY STRUCTURE Good Detached garage INTEGRITY NR SECOND

С

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Parged
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	-
DATE SOURCE	WINDOW MATERIAL 2
Assessor	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Wood	Double hung & fixed
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Wood - shingles	1/1; 1-light
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
1.5	Front gable roof and rectangular massing
ROOF TYPE	ALTERATIONS
Front Gable	Replacement siding; replacement windows in original openings; south dormer addition; front porch removed; wood entry stoop; replacement front door
ROOF MATERIAL	
Asphalt - shingle	

ADDITIONAL PHOTOGRAPHS





Photo Id: first218

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
DEDMIT / HISTO	ADIC INFORMATION
PERMIT/HISTO	DRIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT MOVI	NG INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ODICINAL DED	MIT INFORMATION
ORIGINAL PER	MIT INFORMATION
PULL DANC DEDMIT #	OTHER REPORT INCORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
DATE	#3790 (9/21/1965)2 car frame garage
	COAIMIO
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
BOLEDING PERMIT BESCRIPTION	nistorie ini o
COST	OTHER SOURCES
ORIGINAL OWNER OCCUPIED?	Sanborn Maps1924, 1933, 1948 HISTORIC INFO COMPILER
	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
#3007 (3/28/1962)aluminum siding; removling front porch;	-
pour concrete stoop, iron railing; No permit # (3/3/1958)	[-
garage addition: 81-3 (1/25/1981)fire repair	