Historic Libertyville

CURRENT USE

Domestic - single dwelling

BEGINNING STREET NUMBER 316 **END STREET NUMBER** STREET # SUFFIX **STREET NAME** First Street PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? LOCAL LANDMARK? **YEAR** Photo Id: FirstSt316(1) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING R-7 GROUND FLOOR USE NUMBER OF STORIES Residential UPPER FLOOR USE PROPERTY INDEX NUMBER Residential 1116419002 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No ALTERNATE ADDRESS? NR LANDMARK? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION SECONDARY STRUCTURE Good Detached garage INTEGRITY NR SECOND Minor alterations С

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front Cottage	Parged
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Wood
DATE SOURCE	WINDOW MATERIAL 2
Assessor	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double hung & casement
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	6/1; 1-light
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
1.5	Front gable roof; rectangular massing; hipped-roof porch (enclosed)
ROOF TYPE	
Front Gable	ALTERATIONS
ROOF MATERIAL	Front porch enclosed (post-1948); replacement windows in original openings (casement and fixed); replacement siding (1978)
Asphalt - shingle	

ADDITIONAL PHOTOGRAPHS



Photo Id: FirstSt316(2)

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
PERMIT/HISTOR	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
	IG INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PERM	IIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
7393 (11/26/1973)aluminum siding; 6082 (7/30/1970)install vinyl siding	-