

Historic Libertyville

BEGINNING STREET NUMBER	518
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	Potentially Eligible
CRITERIA	A



Photo Id: FirstSt518(2)

BUILDING DETAILS

BUILDING NAME	-	ZONING	R-7
GROUND FLOOR USE	Residential	NUMBER OF STORIES	2
UPPER FLOOR USE	Residential	PROPERTY INDEX NUMBER	1116408002
CURRENT OCCUPANT	-		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	C	NR ELIGIBLE?	No
WITHIN DISTRICT?	No	CRITERIA	-
NR LANDMARK?	No	ALTERNATE ADDRESS?	-
YEAR	-		

GENERAL INFORMATION

CATEGORY	Building	HISTORIC USE	Domestic - single dwelling
CONDITION	Good	SECONDARY STRUCTURE	Detached garage
INTEGRITY	Minor alterations and additions	NR SECOND	NC
CURRENT USE	Domestic - single dwelling		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Italianate

DETAILS

-

OTHER YEAR

2002

DATE SOURCE

Surveyor/permit

WALL MATERIAL (CURRENT)

Wood

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular

NO OF STORIES

2

ROOF TYPE

Hipped

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Concrete

PORCH

Front entry

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

1/1

SIGNIFICANCE

Fine example Italianate residential architecture in the village, with characteristic bracketed cornice and classical wood window surrounds. The enclosed front porch and open entry porch on the north facade are non-historic alterations.

HISTORIC FEATURES

Shallow hipped roof; wood cornice with scrolled brackets; classical wood window surrounds

ALTERATIONS

Front porch addition (not historic); original north side sun porch removed and replaced with small entry porch (not historic)

ADDITIONAL PHOTOGRAPHS



Photo Id: FirstSt518(3)



Photo Id: First518



Photo Id: First518(2)

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

-

BUILDING MOVED?

Yes

MOVED FROM

Unknown

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

#00-20A (7/15/2002)--detached garage; porch alterations and fence; 85-224 (7/31/1985)--construct outside stair; 77-484 (8/4/1977)--addition (\$15,000)

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

Based on Sanborn maps, it appears that the house was moved from another location some time after 1948. A 1951 permit for a one-story single-family residence was found in the village building files, but the lot number doesn't match that of the subject house. No moving permit was found.

OTHER SOURCES

Sanborn Maps--1924, 1933, 1948 IHSS photograph (mid-1970s)

HISTORIC INFO COMPILER

LR

VOLUNTEER

-