Historic Libertyville

CURRENT USE

Domestic - single dwelling

BEGINNING STREET NUMBER 525 **END STREET NUMBER** STREET # SUFFIX **STREET NAME** First Street PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? NC LOCAL LANDMARK? No **YEAR** Photo Id: FirstSt525(3) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING R-7 GROUND FLOOR USE NUMBER OF STORIES Residential UPPER FLOOR USE PROPERTY INDEX NUMBER Residential 1116405117 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No NR LANDMARK? ALTERNATE ADDRESS? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION SECONDARY STRUCTURE Good Detached garage INTEGRITY NR SECOND NC Major alterations and additions

ARCHITECTURAL DESCRIPTION

Gable Front DETAILS - OTHER YEAR 1990s DATE SOURCE Surveyor/Permits WALL MATERIAL (CURRENT) Not visible PORCH Full Front WINDOW MATERIAL Aluminum/vinyl WINDOW MATERIAL 2 Wood WINDOW TYPE
- Full Front OTHER YEAR 1990s DATE SOURCE Surveyor/Permits WALL MATERIAL (CURRENT) Full Front WINDOW MATERIAL Aluminum/vinyl Wood WINDOW TYPE
OTHER YEAR 1990s DATE SOURCE Surveyor/Permits WINDOW MATERIAL Wood WINDOW TYPE
1990s Aluminum/vinyl DATE SOURCE WINDOW MATERIAL 2 Surveyor/Permits Wood WALL MATERIAL (CURRENT) WINDOW TYPE
DATE SOURCE Surveyor/Permits Wall MATERIAL (CURRENT) WINDOW MATERIAL 2 Wood WINDOW TYPE
Surveyor/Permits Wood WALL MATERIAL (CURRENT) WINDOW TYPE
WALL MATERIAL (CURRENT) WINDOW TYPE
Aluminum/vinyl Double Hung
WALL MATERIAL 2 (CURRENT) WINDOW CONFIGURATION
- 1/1
PLAN SIGNIFICANCE
Irregular -
NO OF STORIES HISTORIC FEATURES
2 Front gable roof; some historic wood windows on first sto
ROOF TYPE ALTERATIONS
Front Gable Original house obscured by multiple additions and alterat
ROOF MATERIAL story south side addition; 2-story rear addition (1992); fr porch replaced (1997); replacement siding (1983); repla
Asphalt - shingle windows in original openings; skylight

ADDITIONAL PHOTOGRAPHS



Photo Id: FirstSt525(2)



Photo Id: FirstStreet525



Photo Id: FirstStreet525(1)

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
PERMIT/HISTOI	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
<u>PERMIT MOVIN</u>	<u>IG INFORMATION</u>
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PERM	MIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps1924, 1933, 1948
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
93-158 (4/26/1983)replace siding and roofing; 92-253 (5/15/1992)2nd story addition over existing first story (singlefamily dwelling); 97-760 (9/30/1997)1-story frame addition and frame porch	-