

Historic Libertyville

BEGINNING STREET NUMBER	<input type="text" value="615"/>
END STREET NUMBER	<input type="text" value="-"/>
STREET # SUFFIX	<input type="text" value="-"/>
STREET NAME	<input type="text" value="First Street"/>
PIN	<input type="text"/>
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	<input type="text" value="No"/>
LOCAL DIST CONTRIB/NON-CONTRIB?	<input type="text" value="C"/>
LOCAL LANDMARK?	<input type="text" value="No"/>
YEAR	<input type="text" value="-"/>
LOCAL LANDMARK ELIGIBLE?	<input type="text" value="No"/>
CRITERIA	<input type="text" value="-"/>



Photo Id: FirstSt615(1)

BUILDING DETAILS

BUILDING NAME	<input type="text" value="-"/>
GROUND FLOOR USE	<input type="text" value="Residential"/>
UPPER FLOOR USE	<input type="text" value="Residential"/>
CURRENT OCCUPANT	<input type="text" value="-"/>

ZONING	<input type="text" value="R-7"/>
NUMBER OF STORIES	<input type="text" value="1.5"/>
PROPERTY INDEX NUMBER	<input type="text" value="1116405046"/>

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	<input type="text" value="C"/>
WITHIN DISTRICT?	<input type="text" value="No"/>
NR LANDMARK?	<input type="text" value="No"/>
YEAR	<input type="text" value="-"/>

NR ELIGIBLE?	<input type="text" value="No"/>
CRITERIA	<input type="text" value="-"/>
ALTERNATE ADDRESS?	<input type="text" value="-"/>

GENERAL INFORMATION

CATEGORY	<input type="text" value="Building"/>
CONDITION	<input type="text" value="Good"/>
INTEGRITY	<input type="text" value="Minor alterations and additions"/>
CURRENT USE	<input type="text" value="Domestic - single dwelling"/>

HISTORIC USE	<input type="text" value="Domestic - single dwelling"/>
SECONDARY STRUCTURE	<input type="text" value="-"/>
NR SECOND	<input type="text" value="-"/>

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Bungalow

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Owner (house history)

WALL MATERIAL (CURRENT)

Stucco

WALL MATERIAL 2 (CURRENT)

Wood

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Concrete-block

PORCH

Full Front

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double hung & casement

WINDOW CONFIGURATION

1/1; 1-light

SIGNIFICANCE

-

HISTORIC FEATURES

Broad front gable roof with overhanging eaves and exposed rafter tails; full front porch with hipped roof, square piers on solid knee walls; historic 1/1 wood windows

ALTERATIONS

Shed roof front porch on south facade (1960); replacement front door; replacement front porch steps; shed roof dormer addition (1963)

ADDITIONAL PHOTOGRAPHS



Photo Id: FirstSt615(2)



Photo Id: Newberry615



Photo Id: Newberry615(2)

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER