

# Historic Libertyville

<b>BEGINNING STREET NUMBER</b>	<input type="text" value="623"/>
<b>END STREET NUMBER</b>	<input type="text" value="-"/>
<b>STREET # SUFFIX</b>	<input type="text" value="-"/>
<b>STREET NAME</b>	<input type="text" value="First Street"/>
<b>PIN</b>	<input type="text"/>
<b><u>LOCAL</u></b>	
<b>WITHIN LOCAL DISTRICT?</b>	<input type="text" value="No"/>
<b>LOCAL DIST CONTRIB/NON-CONTRIB?</b>	<input type="text" value="NC"/>
<b>LOCAL LANDMARK?</b>	<input type="text" value="No"/>
<b>YEAR</b>	<input type="text" value="-"/>
<b>LOCAL LANDMARK ELIGIBLE?</b>	<input type="text" value="No"/>
<b>CRITERIA</b>	<input type="text" value="-"/>



Photo Id: FirstSt623(1)

## BUILDING DETAILS

<b>BUILDING NAME</b>	<input type="text" value="-"/>
<b>GROUND FLOOR USE</b>	<input type="text" value="Residential"/>
<b>UPPER FLOOR USE</b>	<input type="text" value="Residential"/>
<b>CURRENT OCCUPANT</b>	<input type="text" value="-"/>

<b>ZONING</b>	<input type="text" value="R-7"/>
<b>NUMBER OF STORIES</b>	<input type="text" value="2"/>
<b>PROPERTY INDEX NUMBER</b>	<input type="text" value="1116405044"/>

## NATIONAL REGISTER

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	<input type="text" value="NC"/>
<b>WITHIN DISTRICT?</b>	<input type="text" value="No"/>
<b>NR LANDMARK?</b>	<input type="text" value="No"/>
<b>YEAR</b>	<input type="text" value="-"/>

<b>NR ELIGIBLE?</b>	<input type="text" value="No"/>
<b>CRITERIA</b>	<input type="text" value="-"/>
<b>ALTERNATE ADDRESS?</b>	<input type="text" value="-"/>

## GENERAL INFORMATION

<b>CATEGORY</b>	<input type="text" value="Building"/>
<b>CONDITION</b>	<input type="text" value="Excellent"/>
<b>INTEGRITY</b>	<input type="text" value="Major alterations and additions"/>
<b>CURRENT USE</b>	<input type="text" value="Domestic - single dwelling"/>

<b>HISTORIC USE</b>	<input type="text" value="Domestic - single dwelling"/>
<b>SECONDARY STRUCTURE</b>	<input type="text" value="Detached garage"/>
<b>NR SECOND</b>	<input type="text" value="NC"/>

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Side Gable

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Surveyor

## **WALL MATERIAL (CURRENT)**

Hardie board

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

Rectangular

## **NO OF STORIES**

2

## **ROOF TYPE**

Side Gable

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Not visible

## **PORCH**

Full Front

## **WINDOW MATERIAL**

Aluminum/vinyl

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

Double Hung

## **WINDOW CONFIGURATION**

multi-light/multi-light

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

Side gable roof with intersecting front gable centered along front facade

## **ALTERATIONS**

Replacement siding (2014); replacement windows in original openings (2014); replacement front door (2014); replacement front porch (1993); 2-story rear addition (2015)

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: FirstSt623(2)



Photo Id: First623(2)



Photo Id: First623



Photo Id: First623(3)

## HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

## PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

## PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

## ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

93-309 (1993)--rebuilt existing porch; JLC-11-0152 (2011)--remove rear deck and replace with patio; JRE-14-0058 (2014)--repair porch, replace door, windows and siding; JRA-14-0029 (2015)--addition and remodel, detached garage

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER