

Historic Libertyville

BEGINNING STREET NUMBER	136
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Newberry Avenue
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	Potentially Eligible
CRITERIA	A



Photo Id: NewberryAve136(1)

BUILDING DETAILS

BUILDING NAME	ZONING
-	R-7
GROUND FLOOR USE	NUMBER OF STORIES
Residential	1
UPPER FLOOR USE	PROPERTY INDEX NUMBER
N/A	1116403006
CURRENT OCCUPANT	
-	

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NR ELIGIBLE?
C	No
WITHIN DISTRICT?	CRITERIA
No	-
NR LANDMARK?	ALTERNATE ADDRESS?
No	-
YEAR	
-	

GENERAL INFORMATION

CATEGORY	HISTORIC USE
Building	Domestic - single dwelling
CONDITION	SECONDARY STRUCTURE
Good	Detached garage
INTEGRITY	NR SECOND
Minor alterations	NC
CURRENT USE	
Domestic - single dwelling	

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Craftsman Bungalow

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

Stucco

PLAN

Irregular

NO OF STORIES

1.5

ROOF TYPE

Side Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Concrete-block

PORCH

Corner entry

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

Aluminum/vinyl

WINDOW TYPE

Double hung, casement & fixed

WINDOW CONFIGURATION

1/1; multi-light; multi-light/1

SIGNIFICANCE

Despite some alterations, this Craftsman Bungalow may be eligible for local landmark designation.

HISTORIC FEATURES

Side gable roof with L brackets under eaves; front gable bay with battered corners, decorative half timbering; east side oriel window bay; corner entry porch with battered square columns; gable front dormer

ALTERATIONS

Replacement siding on sections of exterior; front porch enclosed; alterations to rear porch (replaced 1956, alterations 1970)

ADDITIONAL PHOTOGRAPHS



Photo Id: NewberryAve136(2)



Photo Id: Newberry136

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

No permit # (5/29/1970)--repairing front and rear steps, new decking and rails on rear porch; 1417 (4/28/1956)--new back porch replacing present porch;

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

Sanborn Maps--1912, 1924, 1933, 1948

OTHER SOURCES

-

HISTORIC INFO COMPILER

LR

VOLUNTEER

-