

# Historic Libertyville

BEGINNING STREET NUMBER	121
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	W. Park Avenue
PIN	
<b><u>LOCAL</u></b>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ParkAveW121(2)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	<b>ZONING</b>
-	C-2
<b>GROUND FLOOR USE</b>	<b>NUMBER OF STORIES</b>
Commercial/Office	2
<b>UPPER FLOOR USE</b>	<b>PROPERTY INDEX NUMBER</b>
Unknown	1121211001
<b>CURRENT OCCUPANT</b>	
State Farm Insurance	

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	<b>NR ELIGIBLE?</b>
C	No
<b>WITHIN DISTRICT?</b>	<b>CRITERIA</b>
No	-
<b>NR LANDMARK?</b>	<b>ALTERNATE ADDRESS?</b>
No	-
<b>YEAR</b>	
-	

## **GENERAL INFORMATION**

<b>CATEGORY</b>	<b>HISTORIC USE</b>
Building	Domestic - single dwelling
<b>CONDITION</b>	<b>SECONDARY STRUCTURE</b>
Good	-
<b>INTEGRITY</b>	<b>NR SECOND</b>
Moderate alterations	-
<b>CURRENT USE</b>	
Commerce/Trade - office	

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Cross Gable

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Surveyor

## **WALL MATERIAL (CURRENT)**

Aluminum/vinyl

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

Cross

## **NO OF STORIES**

2

## **ROOF TYPE**

Cross Gable

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Parged

## **PORCH**

Corner entry

## **WINDOW MATERIAL**

Wood

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

Double hung, fixed & casement

## **WINDOW CONFIGURATION**

1/1; multi-light; 1-light

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

Two story front gable bay with east and west two-story cross-bays; cutaway corners on front bay; square, east-side oriel bay with historic wood windows

## **ALTERATIONS**

Replacement siding (2005); replacement windows in downsized openings (except in oriel bay); corner entry porch (historic alteration likely dating from the 1910s or 20s, enclosed later); fixed shutters; rear east-side addition; east deck addition; exterior staircase on west bay (2006)

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: ParkAveW121(1)



Photo Id: WParkAve121



Photo Id: WParkAve121(2)

## **HISTORIC INFORMATION**

**OLD ADDRESS (CITY DIR.YEAR**

-

**BUILDING MOVED?**

-

**MOVED FROM**

-

**ORIGINAL OWNER**

-

**ORIGINAL ARCHITECT**

-

**ARCHITECT SOURCE**

-

**BUILDER**

-

**SURVEYOR**

LR

**SURVEYOR ORGANIZATION**

Ramsey Historic Consultants

**SURVEY DATE**

May-June 2016

**SURVEY AREA**

Downtown Libertyville

## **PERMIT/HISTORIC INFORMATION**

**OLD ADDRESS**

-

**DATE OF CONSTRUCTION**

-

## **PERMIT MOVING INFORMATION**

**MOVING PERMIT #**

-

**DATE MOVED**

-

## **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #**

-

**DATE**

-

**BUILDING PERMIT DESCRIPTION**

-

**COST**

-

**ORIGINAL OWNER OCCUPIED?**

-

**EXTERIOR ALTERATION PERMITS**

85-236 (7/25/1985)--alterations; PB-05-0438 (5/24/2005)--siding; JCM-04-0035 (3/15/2006)--second-floor door, deck & stairs (rear)

**OTHER PERMIT INFORMATION**

-

**COA INFO**

-

**HISTORIC INFO**

-

**OTHER SOURCES**

Sanborn Maps--1924 (Sheet 9); 1933 (Sheet 5); 1948 (Sheet 5)

**HISTORIC INFO COMPILER**

LR

**VOLUNTEER**

-