

# Historic Libertyville

<b>BEGINNING STREET NUMBER</b>	121
<b>END STREET NUMBER</b>	-
<b>STREET # SUFFIX</b>	-
<b>STREET NAME</b>	W. Park Avenue
<b>PIN</b>	
<b><u>LOCAL</u></b>	
<b>WITHIN LOCAL DISTRICT?</b>	No
<b>LOCAL DIST CONTRIB/NON-CONTRIB?</b>	C
<b>LOCAL LANDMARK?</b>	No
<b>YEAR</b>	-
<b>LOCAL LANDMARK ELIGIBLE?</b>	No
<b>CRITERIA</b>	-



Photo Id: ParkAveW121(2)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	-	<b>ZONING</b>	C-2
<b>GROUND FLOOR USE</b>	Commercial/Office	<b>NUMBER OF STORIES</b>	2
<b>UPPER FLOOR USE</b>	Unknown	<b>PROPERTY INDEX NUMBER</b>	1121211001
<b>CURRENT OCCUPANT</b>	State Farm Insurance		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	C	<b>NR ELIGIBLE?</b>	No
<b>WITHIN DISTRICT?</b>	No	<b>CRITERIA</b>	-
<b>NR LANDMARK?</b>	No	<b>ALTERNATE ADDRESS?</b>	-
<b>YEAR</b>	-		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	Building	<b>HISTORIC USE</b>	Domestic - single dwelling
<b>CONDITION</b>	Good	<b>SECONDARY STRUCTURE</b>	-
<b>INTEGRITY</b>	Moderate alterations	<b>NR SECOND</b>	-
<b>CURRENT USE</b>	Commerce/Trade - office		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Cross Gable

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Surveyor

## **WALL MATERIAL (CURRENT)**

Aluminum/vinyl

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

Cross

## **NO OF STORIES**

2

## **ROOF TYPE**

Cross Gable

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Parged

## **PORCH**

Corner entry

## **WINDOW MATERIAL**

Wood

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

Double hung, fixed & casement

## **WINDOW CONFIGURATION**

1/1; multi-light; 1-light

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

Two story front gable bay with east and west two-story cross-bays; cutaway corners on front bay; square, east-side oriel bay with historic wood windows

## **ALTERATIONS**

Replacement siding (2005); replacement windows in downsized openings (except in oriel bay); corner entry porch (historic alteration likely dating from the 1910s or 20s, enclosed later); fixed shutters; rear east-side addition; east deck addition; exterior staircase on west bay (2006)

**ADDITIONAL PHOTOGRAPHS**



Photo Id: ParkAveW121(1)



Photo Id: WParkAve121



Photo Id: WParkAve121(2)

## HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

## PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

## PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

## ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER