

Historic Libertyville

BEGINNING STREET NUMBER	125
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	W. Park Avenue
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ParkAveW125(2)

BUILDING DETAILS

BUILDING NAME	-	ZONING	C-2
GROUND FLOOR USE	Commercial/Office	NUMBER OF STORIES	2
UPPER FLOOR USE	Unknown	PROPERTY INDEX NUMBER	1121109004
CURRENT OCCUPANT	Griswold Home Care		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	C	NR ELIGIBLE?	No
WITHIN DISTRICT?	No	CRITERIA	-
NR LANDMARK?	No	ALTERNATE ADDRESS?	-
YEAR	-		

GENERAL INFORMATION

CATEGORY	Building	HISTORIC USE	Domestic - single dwelling
CONDITION	Good	SECONDARY STRUCTURE	-
INTEGRITY	Moderate alterations	NR SECOND	-
CURRENT USE	Commerce/Trade - office		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Queen Anne/Shingle

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

Wood - shingles

PLAN

Rectangular

NO OF STORIES

2.5

ROOF TYPE

Side Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Parged

PORCH

Full Front

WINDOW MATERIAL

Aluminum/vinyl

WINDOW MATERIAL 2

-

WINDOW TYPE

Double hung & casement

WINDOW CONFIGURATION

1/1; 1-light

SIGNIFICANCE

-

HISTORIC FEATURES

Side gable roof with cornice returns; three-sided east oriel bay window; inset front porch structure (altered)

ALTERATIONS

Sanborn maps from 1924-1948 show house with full-front, open porch--porch partially enclosed at center, removed at west end, with open entry porch at east end; replacement windows in original openings on side elevations; inset porch in front dormer enclosed with casement windows; replacement siding

ADDITIONAL PHOTOGRAPHS



Photo Id: ParkAveW125(1)



Photo Id: Park125W



Photo Id: WParkAve125(2)

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

JCM-13-0028 (1/2/2014)--three replacement windows in apartment; 99-732 (7/22/1999)--addition; architectural drawing (no date)--alterations to rear facade (replacement siding, 2nd-story door and exterior staircase)

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

Sanborn Maps--1924 (Sheet 9); 1933 (Sheet 5); 1948 (Sheet 5)
Mid-1970s photograph from IHSS

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER