## **Historic Libertyville**

Commerce/Trade

**BEGINNING STREET NUMBER** 207 **END STREET NUMBER** STREET # SUFFIX **STREET NAME** E. Park Avenue PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? LOCAL LANDMARK? **YEAR** Photo Id: ParkAveE207(4) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING C-2 GROUND FLOOR USE NUMBER OF STORIES Office UPPER FLOOR USE PROPERTY INDEX NUMBER Office 1121212008 CURRENT OCCUPANT Natural Health Chiropractic **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No ALTERNATE ADDRESS? NR LANDMARK? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION SECONDARY STRUCTURE Good Detached garage INTEGRITY NR SECOND Moderate alterations С **CURRENT USE** 

## **ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front Cottage	Concrete-block
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double hung & fixed
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1; 1-light
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
1.5	Front gable roof and rectangular massing; hipped-roof full-front
ROOF TYPE	porch structure (enclosed)
Front Gable	ALTERATIONS
ROOF MATERIAL	Replacement siding (1994); replacement windows in original openings; front porch enclosed (two door openings, one picture
	openings, mont portri enclosed (two door openings, one picture

window); fixed shutters

Asphalt - shingle

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: ParkAveE207



Photo Id: EParkAve207(2)



Photo Id: EParkAve207

## **HISTORIC INFORMATION**

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
<u>PERMIT/</u>	HISTORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDMIT	MOVING INFORMATION
PERMII	MOVING INFORMATION
MOVING REPAIR #	DATE MOVED
MOVING PERMIT #	DATE MOVED
-	
ORIGINA	AL PERMIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	94-159 (4/13/1994)install vinyl siding, soffit, fascia, and
DATE	gutters; 6955 (9/11/1973)remove existing O. H. Dor and
-	install plate glass window
BUILDING PERMIT DESCRIPTION	COA INFO
COST	HISTORIC INFO
ODICINAL OWNER OCCUPIEDS	OTHER SOURCES
ORIGINAL OWNER OCCUPIED?	Sanborn Maps1933, 1948
[-	HISTORIC INFO COMPILER
EXTERIOR ALTERATION PERMITS	LR
-	VOLUNTEER
	-