

# Historic Libertyville

<b>BEGINNING STREET NUMBER</b>	<input type="text" value="225"/>
<b>END STREET NUMBER</b>	<input type="text" value="-"/>
<b>STREET # SUFFIX</b>	<input type="text" value="-"/>
<b>STREET NAME</b>	<input type="text" value="W. Park Avenue"/>
<b>PIN</b>	<input type="text"/>
<b><u>LOCAL</u></b>	
<b>WITHIN LOCAL DISTRICT?</b>	<input type="text" value="No"/>
<b>LOCAL DIST CONTRIB/NON-CONTRIB?</b>	<input type="text" value="C"/>
<b>LOCAL LANDMARK?</b>	<input type="text" value="No"/>
<b>YEAR</b>	<input type="text" value="-"/>
<b>LOCAL LANDMARK ELIGIBLE?</b>	<input type="text" value="No"/>
<b>CRITERIA</b>	<input type="text" value="-"/>



Photo Id: ParkAveW225(1)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	<input type="text" value="-"/>	<b>ZONING</b>	<input type="text" value="R-8"/>
<b>GROUND FLOOR USE</b>	<input type="text" value="Residential Apartments"/>	<b>NUMBER OF STORIES</b>	<input type="text" value="2"/>
<b>UPPER FLOOR USE</b>	<input type="text" value="Residential Apartments"/>	<b>PROPERTY INDEX NUMBER</b>	<input type="text" value="1121108018"/>
<b>CURRENT OCCUPANT</b>	<input type="text" value="-"/>		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	<input type="text" value="C"/>	<b>NR ELIGIBLE?</b>	<input type="text" value="No"/>
<b>WITHIN DISTRICT?</b>	<input type="text" value="No"/>	<b>CRITERIA</b>	<input type="text" value="-"/>
<b>NR LANDMARK?</b>	<input type="text" value="No"/>	<b>ALTERNATE ADDRESS?</b>	<input type="text" value="-"/>
<b>YEAR</b>	<input type="text" value="-"/>		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	<input type="text" value="Building"/>	<b>HISTORIC USE</b>	<input type="text" value="Domestic - single dwelling"/>
<b>CONDITION</b>	<input type="text" value="Good"/>	<b>SECONDARY STRUCTURE</b>	<input type="text" value="Detached garage"/>
<b>INTEGRITY</b>	<input type="text" value="Minor alterations"/>	<b>NR SECOND</b>	<input type="text" value="C"/>
<b>CURRENT USE</b>	<input type="text" value="Domestic - multiple dwelling"/>		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Gable Front

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Surveyor

## **WALL MATERIAL (CURRENT)**

Wood - shingles

## **WALL MATERIAL 2 (CURRENT)**

Wood

## **PLAN**

Rectangular

## **NO OF STORIES**

2.5

## **ROOF TYPE**

Front Gable

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Concrete-block

## **PORCH**

Full Front

## **WINDOW MATERIAL**

Wood

## **WINDOW MATERIAL 2**

Aluminum/vinyl

## **WINDOW TYPE**

Double Hung

## **WINDOW CONFIGURATION**

1/1

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

Front gable roof with cornice returns; hipped-roof front porch structure; gable through-the-cornice dormers on side facades; one-story, three-sided window bay on east facade

## **ALTERATIONS**

Replacement windows in original openings; front porch enclosed with aluminum/vinyl windows (1970); fixed shutters; concrete steps (1970)

**ADDITIONAL PHOTOGRAPHS**



Photo Id: ParkAveW225(2)



Photo Id: ParkAveW225



Photo Id: Park225W

## HISTORIC INFORMATION

**OLD ADDRESS (CITY DIR.YEAR)**

**BUILDING MOVED?**

**MOVED FROM**

**ORIGINAL OWNER**

**ORIGINAL ARCHITECT**

**ARCHITECT SOURCE**

**BUILDER**

**SURVEYOR**

**SURVEYOR ORGANIZATION**

**SURVEY DATE**

**SURVEY AREA**

## PERMIT/HISTORIC INFORMATION

**OLD ADDRESS**

**DATE OF CONSTRUCTION**

## PERMIT MOVING INFORMATION

**MOVING PERMIT #**

**DATE MOVED**

## ORIGINAL PERMIT INFORMATION

**BUILDING PERMIT #**

**DATE**

**BUILDING PERMIT DESCRIPTION**

**COST**

**ORIGINAL OWNER OCCUPIED?**

**EXTERIOR ALTERATION PERMITS**

**OTHER PERMIT INFORMATION**

**COA INFO**

**HISTORIC INFO**

**OTHER SOURCES**

**HISTORIC INFO COMPILER**

**VOLUNTEER**