## **Historic Libertyville**

Domestic - multiple dwelling

**BEGINNING STREET NUMBER** 311 **END STREET NUMBER** STREET # SUFFIX **STREET NAME** W. Park Avenue PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? NC LOCAL LANDMARK? **YEAR** Photo Id: ParkAveW311(3) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING R-7 GROUND FLOOR USE NUMBER OF STORIES Residential UPPER FLOOR USE PROPERTY INDEX NUMBER Residential 1121108015 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No NR LANDMARK? ALTERNATE ADDRESS? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION SECONDARY STRUCTURE Fair Coach house INTEGRITY NR SECOND Major alterations **CURRENT USE** 

## **ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Italianate	Brick
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
1930 (c)	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Surveyor	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Aluminum/vinyl	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
Irregular	-
NO OF STORIES	HISTORIC FEATURES
2	Hipped roof; two-story east bay
ROOF TYPE	ALTERATIONS
Hipped	Replacement siding (1990); replacement windows in original openings (not historic); front entry bay addition (open porch addition built c. 1930 and later enclosed); fixed shutters; two-story west addition that is flush with front facade (historic additionc. 1930)
ROOF MATERIAL	
Asphalt - shingle	

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: ParkAveW311(2)



Photo Id: ParkAveW311(4)



Photo Id: wpark311

## **HISTORIC INFORMATION**

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
_	
DEDMIT/HISTO	ORIC INFORMATION
PERMIT/IIISTO	ORIC INI ORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT MOVI	NG INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PER	MIT INFORMATION
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	-
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps1933 (Sheet 9); 1948 (Sheet 9)
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
-	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
No Permit # (5/18/1953)asbestos shingles on exterior of	-
house; 90-674 (12/20/1990)residing duplex, aluminum fascia,	L
soffit, gutter and downspout	