Historic Libertyville

| BEGINNING STREET NUMBER | 317 | |
|---------------------------------|----------------|--|
| END STREET NUMBER | - | |
| STREET # SUFFIX | - | |
| STREET NAME | W. Park Avenue | |
| PIN | | |
| LOCAL | | |
| WITHIN LOCAL DISTRICT? | No | |
| LOCAL DIST CONTRIB/NON-CONTRIB? | С | |
| LOCAL LANDMARK? | No | |
| YEAR | - | |
| LOCAL LANDMARK ELIGIBLE? | Yes | |
| CRITERIA | А | |



Photo Id: ParkAveW317(2)

BUILDING DETAILS

| ZONING |
|-----------------------|
| R-7 |
| NUMBER OF STORIES |
| 1.5 |
| PROPERTY INDEX NUMBER |
| 1121108013 |
| |
| |
| |

NATIONAL REGISTER

| NR DISTRICT CONTRIB/NON-CONTRIB | | |
|---------------------------------|----------|--|
| с | | |
| WITHIN D | ISTRICT? | |
| No | | |
| NR LANDM | IARK? | |
| No | | |
| YEAR | | |
| - | | |
| | | |

NR ELIGIBLE?

No CRITERIA

-

ALTERNATE ADDRESS?

GENERAL INFORMATION

| CATEGORY | |
|----------------------------|--|
| Building | |
| CONDITION | |
| Good | |
| INTEGRITY | |
| Minor alterations | |
| CURRENT USE | |
| Domestic - single dwelling | |

HISTORIC USE

Domestic - single dwelling

SECONDARY STRUCTURE

[attached garage]

NR SECOND

-

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Tudor Revival

DETAILS

OTHER YEAR

-

DATE SOURCE

Assessor/Sanborn Maps

WALL MATERIAL (CURRENT)

Stucco

WALL MATERIAL 2 (CURRENT)

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

Multi-gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Parged

PORCH

Front entry

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double hung & other

WINDOW CONFIGURATION

6/6; multi-light

SIGNIFICANCE

Modest but nicely detailed Tudor Revival cottage from the early post-war period.

HISTORIC FEATURES

Side gable roof; broad front gable bay with decorative half timbering; inset corner entry porch with square wood supports; east end chimney; three-sided oriel bay on east facade; historic wood plank door; wood windows; garage bay at west facade

ALTERATIONS

Replacement front steps to west side entry

ADDITIONAL PHOTOGRAPHS



Photo Id: ParkAveW317(1)



Photo Id: Park317W

HISTORIC INFORMATION

| OLD ADDRESS (CITY DIR.YEAR | BUILDER |
|-----------------------------|---|
| - | - |
| BUILDING MOVED? | SURVEYOR |
| - | LR |
| MOVED FROM | SURVEYOR ORGANIZATION |
| - | Ramsey Historic Consultants |
| ORIGINAL OWNER | SURVEY DATE |
| - | May-June 2016 |
| ORIGINAL ARCHITECT | SURVEY AREA |
| - | Downtown Libertyville |
| ARCHITECT SOURCE | |
| - | |
| | |
| PERMIT/ | HISTORIC INFORMATION |
| | |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| - | - |
| PERMIT | MOVING INFORMATION |
| MOVING PERMIT # | DATE MOVED |
| - | - |
| ORIGINA | L PERMIT INFORMATION |
| BUILDING PERMIT # | OTHER PERMIT INFORMATION |
| - | - |
| DATE | COA INFO |
| - | - |
| BUILDING PERMIT DESCRIPTION | HISTORIC INFO |
| | Carborn Mana 1022 (Chaot 0), 1048 (Chaot 0) |

COST

_

_

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

Sanborn Maps--1933 (Sheet 9); 1948 (Sheet 9)

OTHER SOURCES

-

HISTORIC INFO COMPILER

LR VOLUNTEER

-