

# Historic Libertyville

<b>BEGINNING STREET NUMBER</b>	403-405
<b>END STREET NUMBER</b>	-
<b>STREET # SUFFIX</b>	-
<b>STREET NAME</b>	W. Park Avenue
<b>PIN</b>	
<b><u>LOCAL</u></b>	
<b>WITHIN LOCAL DISTRICT?</b>	No
<b>LOCAL DIST CONTRIB/NON-CONTRIB?</b>	C
<b>LOCAL LANDMARK?</b>	No
<b>YEAR</b>	-
<b>LOCAL LANDMARK ELIGIBLE?</b>	Yes
<b>CRITERIA</b>	A



Photo Id: ParkAveW403-405(1)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	-	<b>ZONING</b>	R-7
<b>GROUND FLOOR USE</b>	Residential Apartments	<b>NUMBER OF STORIES</b>	2
<b>UPPER FLOOR USE</b>	Residential Apartments	<b>PROPERTY INDEX NUMBER</b>	-
<b>CURRENT OCCUPANT</b>	-		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	C	<b>NR ELIGIBLE?</b>	No
<b>WITHIN DISTRICT?</b>	No	<b>CRITERIA</b>	-
<b>NR LANDMARK?</b>	No	<b>ALTERNATE ADDRESS?</b>	-
<b>YEAR</b>	-		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	Building	<b>HISTORIC USE</b>	Domestic - multiple dwelling
<b>CONDITION</b>	Good	<b>SECONDARY STRUCTURE</b>	Detached garage
<b>INTEGRITY</b>	Minor alterations	<b>NR SECOND</b>	C
<b>CURRENT USE</b>	Domestic - multiple dwelling		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Craftsman

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Surveyor

## **WALL MATERIAL (CURRENT)**

Stucco

## **WALL MATERIAL 2 (CURRENT)**

Brick

## **PLAN**

Rectangular

## **NO OF STORIES**

2

## **ROOF TYPE**

Hipped

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Brick

## **PORCH**

Multiple entries

## **WINDOW MATERIAL**

Wood

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

Double Hung

## **WINDOW CONFIGURATION**

3/1; 5/1

## **SIGNIFICANCE**

Fine Craftsman duplex with mirror-image entry porches on either side of a central hipped-roof bay.

## **HISTORIC FEATURES**

Two-story hipped front bay flanked by matching entry porches (porches feature brick knee walls, battered piers, hipped roof); overhanging eaves; stucco cladding; west secondary entrance with shed canopy; historic wood windows

## **ALTERATIONS**

Replacement railings on front steps

**ADDITIONAL PHOTOGRAPHS**



Photo Id: ParkAveW403-405(3)



Photo Id: WParkAve403405

## HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

## PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

## PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

## ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER