## **Historic Libertyville**

Domestic - multiple dwelling

**BEGINNING STREET NUMBER** 423 **END STREET NUMBER** STREET # SUFFIX **STREET NAME** W. Park Avenue PIN **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? C LOCAL LANDMARK? **YEAR** Photo Id: ParkAveW423(1) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING R-7 GROUND FLOOR USE NUMBER OF STORIES Residential UPPER FLOOR USE PROPERTY INDEX NUMBER Residential 1121108007 CURRENT OCCUPANT **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No ALTERNATE ADDRESS? NR LANDMARK? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Domestic - single dwelling CONDITION SECONDARY STRUCTURE Good Barn INTEGRITY NR SECOND Minor alterations and additions **CURRENT USE** 

## **ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Italianate	Brick
DETAILS	PORCH
-	Corner entry
OTHER YEAR	WINDOW MATERIAL
1910	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Surveyor/Assessor	Aluminum/vinyl
WALL MATERIAL (CURRENT)	WINDOW TYPE
Wood - shingles	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1/1
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
2	Hipped roof; cornice with paneled frieze and brackets; classical
ROOF TYPE	lintels over windows and doors with bulls eye corner blocks; corner entry porch; some wood 1/1 windows on 2nd story (historic, but likely not original)
Hipped	
ROOF MATERIAL	ALTERATIONS

Asphalt - shingle

Replacement siding; some 1/1 replacement windows in original openings; replacement railing and deck on porch; replacement front door; rear east porch enclosed; fixed shutters; one-story west addition; west side stair addition

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: ParkAveW423(2)



Photo Id: WPark423



Photo Id: WPark423(2)

## **HISTORIC INFORMATION**

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
DEDMIT /	IICTORIC INFORMATION
PERMII/I	HISTORIC INFORMATION
0.5.45556	2.22.22.22.22.22.22.22.22.22.22.22.22.2
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
PERMIT	MOVING INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ODICINA	
<u>ORIGINA</u>	<u>L PERMIT INFORMATION</u>
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	
DATE	COA INFO
-	-
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	Sanborn Maps1933 (Sheet 9); 1948 (Sheet 9)
COST	OTHER SOURCES
-	-
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
-	-