

Historic Libertyville

| | |
|--|--|
| BEGINNING STREET NUMBER | <input type="text" value="123"/> |
| END STREET NUMBER | <input type="text" value="-"/> |
| STREET # SUFFIX | <input type="text" value="-"/> |
| STREET NAME | <input type="text" value="W. Maple Avenue"/> |
| PIN | <input type="text"/> |
| <u>LOCAL</u> | |
| WITHIN LOCAL DISTRICT? | <input type="text" value="No"/> |
| LOCAL DIST CONTRIB/NON-CONTRIB? | <input type="text" value="NC"/> |
| LOCAL LANDMARK? | <input type="text" value="No"/> |
| YEAR | <input type="text" value="-"/> |
| LOCAL LANDMARK ELIGIBLE? | <input type="text" value="No"/> |
| CRITERIA | <input type="text" value="-"/> |



Photo Id: maple123

BUILDING DETAILS

| | | | |
|-------------------------|--|------------------------------|---|
| BUILDING NAME | <input type="text" value="-"/> | ZONING | <input type="text" value="R-8"/> |
| GROUND FLOOR USE | <input type="text" value="Residential"/> | NUMBER OF STORIES | <input type="text" value="2"/> |
| UPPER FLOOR USE | <input type="text" value="Residential"/> | PROPERTY INDEX NUMBER | <input type="text" value="1116316003"/> |
| CURRENT OCCUPANT | <input type="text" value="-"/> | | |

NATIONAL REGISTER

| | | | |
|--|---------------------------------|---------------------------|---------------------------------|
| NR DISTRICT CONTRIB/NON-CONTRIB | <input type="text" value="NC"/> | NR ELIGIBLE? | <input type="text" value="No"/> |
| WITHIN DISTRICT? | <input type="text" value="No"/> | CRITERIA | <input type="text" value="-"/> |
| NR LANDMARK? | <input type="text" value="No"/> | ALTERNATE ADDRESS? | <input type="text" value="-"/> |
| YEAR | <input type="text" value="-"/> | | |

GENERAL INFORMATION

| | | | |
|--------------------|--|----------------------------|---|
| CATEGORY | <input type="text" value="Building"/> | HISTORIC USE | <input type="text" value="Domestic - single dwelling"/> |
| CONDITION | <input type="text" value="Good"/> | SECONDARY STRUCTURE | <input type="text" value="-"/> |
| INTEGRITY | <input type="text" value="Major alterations and additions"/> | NR SECOND | <input type="text" value="-"/> |
| CURRENT USE | <input type="text" value="Domestic - multiple dwelling"/> | | |

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Queen Anne

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Surveyor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

-

PLAN

irregular

NO OF STORIES

2.5

ROOF TYPE

-

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Not visible

PORCH

-

WINDOW MATERIAL

Aluminum/vinyl

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

1/1

SIGNIFICANCE

-

HISTORIC FEATURES

Hipped main roof; large 2-story front gable bay at north end; 2-story east bay with cutaway corners; west side gable dormer window

ALTERATIONS

Replacement siding; original wraparound porch removed (post-1948); 1-story east side addition (may have originally been part of porch that was enclosed); replacement windows, most in original openings; 1st story front window in altered opening; replacement front door and surround, concrete stoop (1950s); concrete stoop and door at west elevation

ADDITIONAL PHOTOGRAPHS



Photo Id: MapleAveW123(2)



Photo Id: MapleAveW123(3)

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

#1907 (9/16/1957)--enlarge first floor living quarters; create two apartments on 2nd floor; #6945 (8/30/1972)--close malliun window on east wall of living room, move corner windows on north wall to the west 4', lower center window to correspond with door height

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER