

Historic Libertyville

| | |
|---------------------------------|-----------------|
| BEGINNING STREET NUMBER | 127 |
| END STREET NUMBER | - |
| STREET # SUFFIX | - |
| STREET NAME | W. Maple Avenue |
| PIN | |
| <u>LOCAL</u> | |
| WITHIN LOCAL DISTRICT? | No |
| LOCAL DIST CONTRIB/NON-CONTRIB? | NC |
| LOCAL LANDMARK? | No |
| YEAR | - |
| LOCAL LANDMARK ELIGIBLE? | No |
| CRITERIA | - |



Photo Id: MapleAveW127(1)

BUILDING DETAILS

| | |
|-------------------------|------------------------------|
| BUILDING NAME | ZONING |
| - | R-8 |
| GROUND FLOOR USE | NUMBER OF STORIES |
| Residential | 2 |
| UPPER FLOOR USE | PROPERTY INDEX NUMBER |
| Residential | 1116316002 |
| CURRENT OCCUPANT | |
| - | |

NATIONAL REGISTER

| | |
|--|---------------------------|
| NR DISTRICT CONTRIB/NON-CONTRIB | NR ELIGIBLE? |
| NC | No |
| WITHIN DISTRICT? | CRITERIA |
| No | - |
| NR LANDMARK? | ALTERNATE ADDRESS? |
| No | - |
| YEAR | |
| - | |

GENERAL INFORMATION

| | |
|---------------------------------|----------------------------|
| CATEGORY | HISTORIC USE |
| Building | Domestic - single dwelling |
| CONDITION | SECONDARY STRUCTURE |
| Good | - |
| INTEGRITY | NR SECOND |
| Minor alterations and additions | - |
| CURRENT USE | |
| Domestic - single dwelling | |

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Gabled Ell

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

-

PLAN

Irregular

NO OF STORIES

2

ROOF TYPE

Multi-gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Parged

PORCH

Corner entry

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

1/1

SIGNIFICANCE

-

HISTORIC FEATURES

2-story front gable bay intersected by east side, 2-story gabled ell with cutaway corners

ALTERATIONS

Replacement front porch; replacement siding (2003); 2-story rear addition; 1-story west side addition; replacement windows, most in original openings; three-part window at first story of front facade

ADDITIONAL PHOTOGRAPHS



Photo Id: MapleAveW127(3)



Photo Id: maple127

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

#2416 (6/25/1959)--addition; #6146 (10/12/1970)--
greenhouse; PB-03-1308 (10/31/2003)--siding

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

-

OTHER SOURCES

Sanborn Maps--1924, 1933, 1948

HISTORIC INFO COMPILER

LR

VOLUNTEER

-