

Historic Libertyville

BEGINNING STREET NUMBER	133
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	W. Maple Avenue
PIN	

LOCAL

WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: MapleAveW133(1)

BUILDING DETAILS

BUILDING NAME	-
GROUND FLOOR USE	Residential
UPPER FLOOR USE	Residential
CURRENT OCCUPANT	-

ZONING	R-8
NUMBER OF STORIES	2
PROPERTY INDEX NUMBER	1116316001

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	C
WITHIN DISTRICT?	No
NR LANDMARK?	No
YEAR	-

NR ELIGIBLE?	No
CRITERIA	-
ALTERNATE ADDRESS?	-

GENERAL INFORMATION

CATEGORY	Building
CONDITION	Good
INTEGRITY	Minor alterations
CURRENT USE	Domestic - single dwelling

HISTORIC USE	Domestic - single dwelling
SECONDARY STRUCTURE	Detached garage
NR SECOND	C

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Gabled Ell

DETAILS

Queen Anne

OTHER YEAR

-

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Wood

WALL MATERIAL 2 (CURRENT)

Wood

PLAN

T

NO OF STORIES

2

ROOF TYPE

Cross Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Parged

PORCH

Front entry

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

Aluminum/vinyl

WINDOW TYPE

Double hung & other

WINDOW CONFIGURATION

-

SIGNIFICANCE

-

HISTORIC FEATURES

Front gable bay intersected by west-side gable ell; with cutaway corners and sunburst ornament under gable; 2-story square gable bay on east facade; historic wood surrounds and lintels on window openings

ALTERATIONS

Hipped roof front entry porch and front sun porch are historic alterations (replaced original wraparound front porch some time between 1924 and 1933); 1/1 replacement windows in original openings (not historic)

ADDITIONAL PHOTOGRAPHS



Photo Id: MapleAveW133(2)



Photo Id: maple133



Photo Id: MapleAveW133(3)



Photo Id: maple133(2)

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

No Permit # (2/17/1955)--replace obsolete heating unit

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

-

OTHER SOURCES

Sanborn maps--1924, 1933, 1948

HISTORIC INFO COMPILER

LR

VOLUNTEER

-