

Historic Libertyville

BEGINNING STREET NUMBER	216
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Park Place
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ParkPIN216(1)

BUILDING DETAILS

BUILDING NAME	-	ZONING	R-7
GROUND FLOOR USE	Residential	NUMBER OF STORIES	2.5
UPPER FLOOR USE	-	PROPERTY INDEX NUMBER	1116422009
CURRENT OCCUPANT	-		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	C	NR ELIGIBLE?	No
WITHIN DISTRICT?	No	CRITERIA	-
NR LANDMARK?	No	ALTERNATE ADDRESS?	-
YEAR	-		

GENERAL INFORMATION

CATEGORY	Building	HISTORIC USE	Domestic - single dwelling
CONDITION	Good	SECONDARY STRUCTURE	Detached garage
INTEGRITY	Minor alterations	NR SECOND	C
CURRENT USE	Domestic - single dwelling		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Gable Front

DETAILS

Craftsman

OTHER YEAR

-

DATE SOURCE

Sanborn maps (1924, 1933)

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular

NO OF STORIES

2.5

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Concrete-block

PORCH

Corner entry

WINDOW MATERIAL

Aluminum/vinyl

WINDOW MATERIAL 2

Wood

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

6/6; 3/1; 2/1

SIGNIFICANCE

-

HISTORIC FEATURES

Front gable bay with inset corner entry porch; 3/1 and 2/1 wood windows enclosing porch

ALTERATIONS

Replacement siding; replacement windows in original openings

ADDITIONAL PHOTOGRAPHS



Photo Id: ParkPIN216



Photo Id: ParkPI216

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

2732 (8/26/1960)--construction of concrete stair; No permit # (6/11/1959)--removing old chimney, repair back steps, move one door and one window in rear

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

Sanborn Maps--1924 (Sheet 6), 1933 (Sheet 5), 1948 (Sheet 5)

OTHER SOURCES

-

HISTORIC INFO COMPILER

LR

VOLUNTEER

-