

Historic Libertyville

| | |
|---------------------------------|----------------|
| BEGINNING STREET NUMBER | 201 |
| END STREET NUMBER | - |
| STREET # SUFFIX | - |
| STREET NAME | Stewart Avenue |
| PIN | |
| <u>LOCAL</u> | |
| WITHIN LOCAL DISTRICT? | No |
| LOCAL DIST CONTRIB/NON-CONTRIB? | C |
| LOCAL LANDMARK? | No |
| YEAR | - |
| LOCAL LANDMARK ELIGIBLE? | Yes |
| CRITERIA | A |



Photo Id: StewartAveN201(2)

BUILDING DETAILS

| | |
|-------------------------|------------------------------|
| BUILDING NAME | ZONING |
| - | R-7 |
| GROUND FLOOR USE | NUMBER OF STORIES |
| Residential | 2.5 |
| UPPER FLOOR USE | PROPERTY INDEX NUMBER |
| Residential | 1116315006 |
| CURRENT OCCUPANT | |
| - | |

NATIONAL REGISTER

| | |
|--|---------------------------|
| NR DISTRICT CONTRIB/NON-CONTRIB | NR ELIGIBLE? |
| C | No |
| WITHIN DISTRICT? | CRITERIA |
| No | - |
| NR LANDMARK? | ALTERNATE ADDRESS? |
| No | - |
| YEAR | |
| - | |

GENERAL INFORMATION

| | |
|----------------------------|----------------------------|
| CATEGORY | HISTORIC USE |
| Building | Domestic - single dwelling |
| CONDITION | SECONDARY STRUCTURE |
| Good | - |
| INTEGRITY | NR SECOND |
| Minor alterations | - |
| CURRENT USE | |
| Domestic - single dwelling | |

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Gabled Ell

DETAILS

Queen Anne

OTHER YEAR

-

DATE SOURCE

Surveyor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular/L

NO OF STORIES

2.5

ROOF TYPE

Clipped Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Brick

PORCH

Wrap around

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double hung, fixed & casement

WINDOW CONFIGURATION

1/1; 1-light

SIGNIFICANCE

Even with replacement siding, this Gabled-Ell residence with Queen Anne detailing may be eligible for local landmark designation.

HISTORIC FEATURES

Clipped front gable with south side gable-roof ell; wraparound porch with Ionic columns and historic wood railing; historic wood fixed and double hung windows; historic front door

ALTERATIONS

Replacement siding; concrete front porch steps with wrought iron railing; rear porch addition (1999)

ADDITIONAL PHOTOGRAPHS



Photo Id: StewartAveN201(3)



Photo Id: stewart201

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

-

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

-

DATE

-

BUILDING PERMIT DESCRIPTION

-

COST

-

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

99-1213 (11/24/1999)--rear porch addition

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

Sanborn maps--1924 (Sheet 5 & 9), 1933 (Sheet 5), 1948 (Sheet 5) According to owner's House History form, Ed Sullivan, representative for the 51st district in the IL State Legislature, grew up in the house, and lived in it with his wife and children until the 1980s.

OTHER SOURCES

-

HISTORIC INFO COMPILER

LR

VOLUNTEER

-