

# Historic Libertyville

<b>BEGINNING STREET NUMBER</b>	201
<b>END STREET NUMBER</b>	-
<b>STREET # SUFFIX</b>	-
<b>STREET NAME</b>	Stewart Avenue
<b>PIN</b>	
<b><u>LOCAL</u></b>	
<b>WITHIN LOCAL DISTRICT?</b>	No
<b>LOCAL DIST CONTRIB/NON-CONTRIB?</b>	C
<b>LOCAL LANDMARK?</b>	No
<b>YEAR</b>	-
<b>LOCAL LANDMARK ELIGIBLE?</b>	Yes
<b>CRITERIA</b>	A



Photo Id: StewartAveN201(2)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	-	<b>ZONING</b>	R-7
<b>GROUND FLOOR USE</b>	Residential	<b>NUMBER OF STORIES</b>	2.5
<b>UPPER FLOOR USE</b>	Residential	<b>PROPERTY INDEX NUMBER</b>	1116315006
<b>CURRENT OCCUPANT</b>	-		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	C	<b>NR ELIGIBLE?</b>	No
<b>WITHIN DISTRICT?</b>	No	<b>CRITERIA</b>	-
<b>NR LANDMARK?</b>	No	<b>ALTERNATE ADDRESS?</b>	-
<b>YEAR</b>	-		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	Building	<b>HISTORIC USE</b>	Domestic - single dwelling
<b>CONDITION</b>	Good	<b>SECONDARY STRUCTURE</b>	-
<b>INTEGRITY</b>	Minor alterations	<b>NR SECOND</b>	-
<b>CURRENT USE</b>	Domestic - single dwelling		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Gabled Ell

## **DETAILS**

Queen Anne

## **OTHER YEAR**

-

## **DATE SOURCE**

Surveyor

## **WALL MATERIAL (CURRENT)**

Aluminum/vinyl

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

Rectangular/L

## **NO OF STORIES**

2.5

## **ROOF TYPE**

Clipped Gable

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Brick

## **PORCH**

Wrap around

## **WINDOW MATERIAL**

Wood

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

Double hung, fixed & casement

## **WINDOW CONFIGURATION**

1/1; 1-light

## **SIGNIFICANCE**

Even with replacement siding, this Gabled-Ell residence with Queen Anne detailing may be eligible for local landmark designation.

## **HISTORIC FEATURES**

Clipped front gable with south side gable-roof ell; wraparound porch with Ionic columns and historic wood railing; historic wood fixed and double hung windows; historic front door

## **ALTERATIONS**

Replacement siding; concrete front porch steps with wrought iron railing; rear porch addition (1999)

**ADDITIONAL PHOTOGRAPHS**



Photo Id: StewartAveN201(3)



Photo Id: stewart201

## **HISTORIC INFORMATION**

**OLD ADDRESS (CITY DIR.YEAR)**

**BUILDING MOVED?**

**MOVED FROM**

**ORIGINAL OWNER**

**ORIGINAL ARCHITECT**

**ARCHITECT SOURCE**

**BUILDER**

**SURVEYOR**

**SURVEYOR ORGANIZATION**

**SURVEY DATE**

**SURVEY AREA**

## **PERMIT/HISTORIC INFORMATION**

**OLD ADDRESS**

**DATE OF CONSTRUCTION**

## **PERMIT MOVING INFORMATION**

**MOVING PERMIT #**

**DATE MOVED**

## **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #**

**DATE**

**BUILDING PERMIT DESCRIPTION**

**COST**

**ORIGINAL OWNER OCCUPIED?**

**EXTERIOR ALTERATION PERMITS**

**OTHER PERMIT INFORMATION**

**COA INFO**

**HISTORIC INFO**

**OTHER SOURCES**

**HISTORIC INFO COMPILER**

**VOLUNTEER**