## **Historic Libertyville**

Domestic - single family

BEGINNING STREET NUMBER	150	
END STREET NUMBER	-	
STREET # SUFFIX	-	
STREET NAME	Broadway Avenue	
PIN		
<b>LOCAL</b>		
WITHIN LOCAL DISTRICT?	No	
LOCAL DIST CONTRIB/NON-CONTRIB?	С	
LOCAL LANDMARK?	No	
YEAR	-	
LOCAL LANDMARK ELIGIBLE?	No	Photo Id: BroadwayAve150(2)
CRITERIA	-	
	BUILDI	ING DETAILS
BUILDING NAME		ZONING
-		-
GROUND FLOOR USE		NUMBER OF STORIES
Residence		2
UPPER FLOOR USE		PROPERTY INDEX NUMBER
Residential		1116415019
CURRENT OCCUPANT		1
-		
	<b>NATION</b>	AL REGISTER
NR DISTRICT CONTRIB/NON-CONTRIB		NR ELIGIBLE?
С		No
WITHIN DISTRICT?		CRITERIA
No		-
NR LANDMARK?		ALTERNATE ADDRESS?
No		-
YEAR		1
-		
	GENERAL	<u>INFORMATION</u>
		<del></del>
CATEGORY		HISTORIC USE
Building		Domestic - single family
CONDITION		SECONDARY STRUCTURE
Good		Detached garage
INTEGRITY		NR SECOND
Minor alterations		NC

## **ARCHITECTURAL DESCRIPTION**

ARCHITECTURAL CLASSIFICATION	FOUNDATION
Gable Front	Concrete-block
DETAILS	PORCH
-	Full Front
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Owner	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Stucco	Double Hung
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
Wood	1/1
PLAN	SIGNIFICANCE
L	-
NO OF STORIES	HISTORIC FEATURES
2	Front gable roof; rectangular massing; north side gable
ROOF TYPE	ALTERATIONS
Front Gable	Replacement front porch columns; replacement windows in original openings; replacement front door; picture window under porch
ROOF MATERIAL	
Acabalt chingle	

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: Broadway150

## **HISTORIC INFORMATION**

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
<u>PERMIT/HISTO</u>	RIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDMIT MOVIE	NG INFORMATION
PERMIT MOVI	NG INFORMATION
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PER	MIT INFORMATION
<del></del>	
BUILDING PERMIT #	OTHER PERMIT INFORMATION
-	99-292 (4/30/1999)3 car garage
DATE	COA INFO
	_
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
DOLLDING FERRITI DESCRIFTION	Owner writes on house history form: "Martin Lynch 1909-1952
COST	lived at this house and was one of the earliest rural mail carriers
COST	from the Libertyville post office." House was also featured on
- CONTRACT OWNER OCCUPATED	June 2012 Libertyville Historic Walking Tour.
ORIGINAL OWNER OCCUPIED?	OTHER SOURCES
-	-
EXTERIOR ALTERATION PERMITS	HISTORIC INFO COMPILER
75-392 (9/27/1975)addition (\$3,000); 6313 (5/4/1971)	LR
enclose front porch on three sides; 867 (6/7/1954)new steps and straighten up porch, patch stucco; 92-147 (3/24/1992)	VOLUNTEER
opening up and repairing existing closed in front porch	-