Historic Libertyville

| BEGINNING STREET NUMBER | 227 | |
|---------------------------------|-----------------|--|
| END STREET NUMBER | - | |
| STREET # SUFFIX | - | |
| STREET NAME | Broadway Avenue | |
| PIN | | |
| LOCAL | | |
| WITHIN LOCAL DISTRICT? | No | |
| LOCAL DIST CONTRIB/NON-CONTRIB? | NC | |
| LOCAL LANDMARK? | No | |
| YEAR | - | |
| LOCAL LANDMARK ELIGIBLE? | No | |
| CRITERIA | - | |



Photo Id: broadway227

BUILDING DETAILS

BUILDING NAMEZONINGTriggs, James HouseR-6GROUND FLOOR USENUMBER OF STORIESResidence2UPPER FLOOR USEPROPERTY INDEX NUMBERResidential1116422005CURRENT OCCUPANT-

NATIONAL REGISTER

| NR DISTRICT CONTRIB/NON-CONTRIB | |
|---------------------------------|---|
| NC | |
| WITHIN DISTRICT? | _ |
| No | |
| NR LANDMARK? | _ |
| No | |
| YEAR | _ |
| - | |

NR ELIGIBLE?

No CRITERIA

-

ALTERNATE ADDRESS?

GENERAL INFORMATION

| CATEGORY |
|---------------------------------|
| Building |
| CONDITION |
| Good |
| INTEGRITY |
| Major alterations and additions |
| CURRENT USE |
| Domestic - single dwelling |

HISTORIC USE

Domestic - single dwelling
SECONDARY STRUCTURE

Detached garage

NR SECOND

NC

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Queen Anne

DETAILS

OTHER YEAR

-DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Wood

WALL MATERIAL 2 (CURRENT)

PLAN

Rectangular

NO OF STORIES

2.5

ROOF TYPE

Multi-gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Not visible

PORCH

Front entry

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

Clad Wood

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

1/1

SIGNIFICANCE

-

HISTORIC FEATURES

_

ALTERATIONS

Based on historic photograph of house in Libertyville Illustrated, the house has been extensively altered--large 2-story front and rear additions, front entry and porch moved, materials (wood siding, vergeboard, windows) appear to be new.

ADDITIONAL PHOTOGRAPHS



Photo Id: BroadwayAve227(2)



Photo Id: BroadwayAve227(4)

HISTORIC INFORMATION

| OLD ADDRESS (CITY DIR.YEAR | BUILDER |
|-----------------------------|-----------------------------|
| - | - |
| BUILDING MOVED? | SURVEYOR |
| - | LR |
| MOVED FROM | SURVEYOR ORGANIZATION |
| - | Ramsey Historic Consultants |
| ORIGINAL OWNER | SURVEY DATE |
| - | May-June 2016 |
| ORIGINAL ARCHITECT | SURVEY AREA |
| - | Downtown Libertyville |
| ARCHITECT SOURCE | |
| - | |
| PERMIT/ | HISTORIC INFORMATION |
| OLD ADDRESS | DATE OF CONSTRUCTION |
| - | - |
| PERMIT | MOVING INFORMATION |
| MOVING PERMIT # | DATE MOVED |
| - | - |
| ORIGINA | AL PERMIT INFORMATION |
| | |
| BUILDING PERMIT # | OTHER PERMIT INFORMATION |
| - | 76-117 (3/29/1976)garage |
| DATE | COA INFO |
| - | - |
| BUILDING PERMIT DESCRIPTION | HISTORIC INFO |
| - | - |
| COST | OTHER SOURCES |
| - | - |
| ORIGINAL OWNER OCCUPIED? | HISTORIC INFO COMPILER |
| - | LR |

EXTERIOR ALTERATION PERMITS

JRA-04-0066 (2006)--two-story family room, sun room, bedroom addition

VOLUNTEER