

# Historic Libertyville

BEGINNING STREET NUMBER	214
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Broadway Avenue
PIN	
<b><u>LOCAL</u></b>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: BroadwayAve214(1)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	<b>ZONING</b>
-	R-7
<b>GROUND FLOOR USE</b>	<b>NUMBER OF STORIES</b>
Residence	1.5
<b>UPPER FLOOR USE</b>	<b>PROPERTY INDEX NUMBER</b>
Residential	1116419014
<b>CURRENT OCCUPANT</b>	
-	

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	<b>NR ELIGIBLE?</b>
C	No
<b>WITHIN DISTRICT?</b>	<b>CRITERIA</b>
No	-
<b>NR LANDMARK?</b>	<b>ALTERNATE ADDRESS?</b>
No	-
<b>YEAR</b>	
-	

## **GENERAL INFORMATION**

<b>CATEGORY</b>	<b>HISTORIC USE</b>
Building	Domestic - single dwelling
<b>CONDITION</b>	<b>SECONDARY STRUCTURE</b>
Good	Detached garage
<b>INTEGRITY</b>	<b>NR SECOND</b>
Minor alterations	NC
<b>CURRENT USE</b>	
Domestic - single dwelling	

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Bungalow

## **DETAILS**

Craftsman

## **OTHER YEAR**

-

## **DATE SOURCE**

Assessor

## **WALL MATERIAL (CURRENT)**

Aluminum/vinyl

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

Rectangular

## **NO OF STORIES**

1.5

## **ROOF TYPE**

-

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Not visible

## **PORCH**

Front entry

## **WINDOW MATERIAL**

Wood

## **WINDOW MATERIAL 2**

Aluminum/vinyl

## **WINDOW TYPE**

Double Hung

## **WINDOW CONFIGURATION**

3/1; 4/1

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

Broad side gable roof with long, shed-roof front dormer; inset corner entry porch; 4/1 wood windows on first floor; three-sided window bay on east facade

## **ALTERATIONS**

Replacement siding; replacement windows in dormer; entry porch enclosed

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: BroadwayAve214(2)



Photo Id: broadway214

## **HISTORIC INFORMATION**

**OLD ADDRESS (CITY DIR.YEAR**

-

**BUILDING MOVED?**

-

**MOVED FROM**

-

**ORIGINAL OWNER**

-

**ORIGINAL ARCHITECT**

-

**ARCHITECT SOURCE**

-

**BUILDER**

-

**SURVEYOR**

LR

**SURVEYOR ORGANIZATION**

Ramsey Historic Consultants

**SURVEY DATE**

-

**SURVEY AREA**

Downtown Libertyville

## **PERMIT/HISTORIC INFORMATION**

**OLD ADDRESS**

-

**DATE OF CONSTRUCTION**

-

## **PERMIT MOVING INFORMATION**

**MOVING PERMIT #**

-

**DATE MOVED**

-

## **ORIGINAL PERMIT INFORMATION**

**BUILDING PERMIT #**

-

**DATE**

-

**BUILDING PERMIT DESCRIPTION**

-

**COST**

-

**ORIGINAL OWNER OCCUPIED?**

-

**EXTERIOR ALTERATION PERMITS**

1576 (8/27/1956)--replace two rear kitchen windows

**OTHER PERMIT INFORMATION**

88-477 (7/27/1988)--garage

**COA INFO**

-

**HISTORIC INFO**

-

**OTHER SOURCES**

-

**HISTORIC INFO COMPILER**

LR

**VOLUNTEER**

-