

Historic Libertyville

| | |
|--|----------------|
| BEGINNING STREET NUMBER | 315 |
| END STREET NUMBER | - |
| STREET # SUFFIX | - |
| STREET NAME | W. Park Avenue |
| PIN | |
| <u>LOCAL</u> | |
| WITHIN LOCAL DISTRICT? | No |
| LOCAL DIST CONTRIB/NON-CONTRIB? | C |
| LOCAL LANDMARK? | No |
| YEAR | - |
| LOCAL LANDMARK ELIGIBLE? | No |
| CRITERIA | - |



Photo Id: ParkAveW315(2)

BUILDING DETAILS

| | | | |
|-------------------------|-------------|------------------------------|------------|
| BUILDING NAME | - | ZONING | R-7 |
| GROUND FLOOR USE | Residential | NUMBER OF STORIES | 1.5 |
| UPPER FLOOR USE | Residential | PROPERTY INDEX NUMBER | 1121108014 |
| CURRENT OCCUPANT | - | | |

NATIONAL REGISTER

| | | | |
|--|----|---------------------------|----|
| NR DISTRICT CONTRIB/NON-CONTRIB | C | NR ELIGIBLE? | No |
| WITHIN DISTRICT? | No | CRITERIA | - |
| NR LANDMARK? | No | ALTERNATE ADDRESS? | - |
| YEAR | - | | |

GENERAL INFORMATION

| | | | |
|--------------------|----------------------------|----------------------------|----------------------------|
| CATEGORY | Building | HISTORIC USE | Domestic - single dwelling |
| CONDITION | Good | SECONDARY STRUCTURE | Detached garage |
| INTEGRITY | Minor alterations | NR SECOND | C |
| CURRENT USE | Domestic - single dwelling | | |

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Craftsman Bungalow

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Brick

WALL MATERIAL 2 (CURRENT)

Wood - shingles

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

Side Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Not visible

PORCH

Corner entry

WINDOW MATERIAL

Aluminum/vinyl

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

4/1

SIGNIFICANCE

-

HISTORIC FEATURES

Side gable roof with overhanging eaves and L brackets; gable front dormer; inset corner entry porch with brick pier and knee walls; she-roof square window bay on east facade; oversized brick and wood shingle exterior

ALTERATIONS

Replacement windows in original openings; front porch enclosed

ADDITIONAL PHOTOGRAPHS



Photo Id: ParkAveW315(3)



Photo Id: WPark315

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER