Historic Libertyville

Commerce/Trade - retail

BEGINNING STREET NUMBER 107-109 **END STREET NUMBER** STREET # SUFFIX **STREET NAME** E. Cook Avenue PIN DANCE'N TEES **LOCAL** WITHIN LOCAL DISTRICT? No LOCAL DIST CONTRIB/NON-CONTRIB? NC LOCAL LANDMARK? **YEAR** Photo Id: CookAveE107-109(1) LOCAL LANDMARK ELIGIBLE? No **CRITERIA BUILDING DETAILS BUILDING NAME** ZONING C-1 GROUND FLOOR USE NUMBER OF STORIES Commercial **UPPER FLOOR USE** PROPERTY INDEX NUMBER N/A 1116411001 CURRENT OCCUPANT Dance-N-Trees **NATIONAL REGISTER** NR DISTRICT CONTRIB/NON-CONTRIB NR ELIGIBLE? No WITHIN DISTRICT? CRITERIA No ALTERNATE ADDRESS? NR LANDMARK? No YEAR **GENERAL INFORMATION CATEGORY HISTORIC USE** Building Commerce/Trade CONDITION SECONDARY STRUCTURE Good INTEGRITY NR SECOND Major alterations **CURRENT USE**

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION	FOUNDATION
One Part Commercial Block	Not visible
DETAILS	PORCH
-	-
OTHER YEAR	WINDOW MATERIAL
-	Aluminum/vinyl
DATE SOURCE	WINDOW MATERIAL 2
Surveyor; Sanborn Maps	-
WALL MATERIAL (CURRENT)	WINDOW TYPE
Brick	Storefront
WALL MATERIAL 2 (CURRENT)	WINDOW CONFIGURATION
-	1-light
PLAN	SIGNIFICANCE
Rectangular	-
NO OF STORIES	HISTORIC FEATURES
1	Brick exterior; rectangular massing; metal lintel with tie backs over east storefront; stone stringcourse between storefront leve and parapet wall
ROOF TYPE	
Flat	ALTERATIONS
ROOF MATERIAL	
Not Visible	Replacement storefront windows and doors in altered openings; parapet wall appears rebuilt or added; awning over west storefront

ADDITIONAL PHOTOGRAPHS



Photo Id: CookAveE107-109(2)



Photo Id: ECook107109

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR	BUILDER
-	-
BUILDING MOVED?	SURVEYOR
-	LR
MOVED FROM	SURVEYOR ORGANIZATION
-	Ramsey Historic Consultants
ORIGINAL OWNER	SURVEY DATE
-	May-June 2016
ORIGINAL ARCHITECT	SURVEY AREA
-	Downtown Libertyville
ARCHITECT SOURCE	
-	
<u>PERMIT/HIST</u>	TORIC INFORMATION
OLD ADDRESS	DATE OF CONSTRUCTION
-	-
DEDMIT MOV	/INC INCORMATION
PERMIT MOV	<u>/ING INFORMATION</u>
MOVING PERMIT #	DATE MOVED
-	-
ORIGINAL PE	RMIT INFORMATION
<u> </u>	
BUILDING PERMIT #	OTHER PERMIT INFORMATION
BOILDING FERMIN #	OTHER PERPIT IN ORPATION
DATE	COA INFO
DATE	COA INFO
- DULL DING DEDMIT DESCRIPTION	
BUILDING PERMIT DESCRIPTION	HISTORIC INFO
-	-
COST	OTHER SOURCES
-	Sanborn Maps (1897, 1907, 1912, 1924, 1933, 1948)
ORIGINAL OWNER OCCUPIED?	HISTORIC INFO COMPILER
_	LR
EXTERIOR ALTERATION PERMITS	VOLUNTEER
No permit # (1/6/1976)aluminum door and transom (109)	-