

# Historic Libertyville

<b>BEGINNING STREET NUMBER</b>	<input type="text" value="228"/>
<b>END STREET NUMBER</b>	<input type="text" value="-"/>
<b>STREET # SUFFIX</b>	<input type="text" value="-"/>
<b>STREET NAME</b>	<input type="text" value="First Street"/>
<b>PIN</b>	<input type="text" value=""/>
<b><u>LOCAL</u></b>	
<b>WITHIN LOCAL DISTRICT?</b>	<input type="text" value="No"/>
<b>LOCAL DIST CONTRIB/NON-CONTRIB?</b>	<input type="text" value="NC"/>
<b>LOCAL LANDMARK?</b>	<input type="text" value="No"/>
<b>YEAR</b>	<input type="text" value="-"/>
<b>LOCAL LANDMARK ELIGIBLE?</b>	<input type="text" value="No"/>
<b>CRITERIA</b>	<input type="text" value="-"/>



Photo Id: FirstSt228(1)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	<input type="text" value="-"/>	<b>ZONING</b>	<input type="text" value="R-6"/>
<b>GROUND FLOOR USE</b>	<input type="text" value="Residential"/>	<b>NUMBER OF STORIES</b>	<input type="text" value="2"/>
<b>UPPER FLOOR USE</b>	<input type="text" value="Residential"/>	<b>PROPERTY INDEX NUMBER</b>	<input type="text" value="1116423007"/>
<b>CURRENT OCCUPANT</b>	<input type="text" value="-"/>		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	<input type="text" value="NC"/>	<b>NR ELIGIBLE?</b>	<input type="text" value="No"/>
<b>WITHIN DISTRICT?</b>	<input type="text" value="No"/>	<b>CRITERIA</b>	<input type="text" value="-"/>
<b>NR LANDMARK?</b>	<input type="text" value="No"/>	<b>ALTERNATE ADDRESS?</b>	<input type="text" value="-"/>
<b>YEAR</b>	<input type="text" value="-"/>		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	<input type="text" value="Building"/>	<b>HISTORIC USE</b>	<input type="text" value="Domestic - single dwelling"/>
<b>CONDITION</b>	<input type="text" value="Good"/>	<b>SECONDARY STRUCTURE</b>	<input type="text" value="Detached garage"/>
<b>INTEGRITY</b>	<input type="text" value="Major alterations and additions"/>	<b>NR SECOND</b>	<input type="text" value="NC"/>
<b>CURRENT USE</b>	<input type="text" value="Domestic - single dwelling"/>		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Gable Front

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Assessor

## **WALL MATERIAL (CURRENT)**

Aluminum/vinyl

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

Rectangular

## **NO OF STORIES**

2

## **ROOF TYPE**

Front Gable

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Concrete

## **PORCH**

Full Front

## **WINDOW MATERIAL**

Wood

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

Double hung & fixed

## **WINDOW CONFIGURATION**

1/1; 1-light

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

Front gable roof; rectangular massing

## **ALTERATIONS**

Non-historic alterations include replacement siding; replacement windows in original openings; front porch enclosed; wood steps to front porch entrance; 2-story rear addition; rear deck addition

**ADDITIONAL PHOTOGRAPHS**



Photo Id: FirstSt228(4)



Photo Id: first228

## HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

## PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

## PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

## ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

# Historic Libertyville

BEGINNING STREET NUMBER	315
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<b><u>LOCAL</u></b>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt315(1)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	-	<b>ZONING</b>	R-7
<b>GROUND FLOOR USE</b>	Residential	<b>NUMBER OF STORIES</b>	2
<b>UPPER FLOOR USE</b>	Residential	<b>PROPERTY INDEX NUMBER</b>	1116415016
<b>CURRENT OCCUPANT</b>	-		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	NC	<b>NR ELIGIBLE?</b>	No
<b>WITHIN DISTRICT?</b>	No	<b>CRITERIA</b>	-
<b>NR LANDMARK?</b>	No	<b>ALTERNATE ADDRESS?</b>	-
<b>YEAR</b>	-		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	Building	<b>HISTORIC USE</b>	Domestic - single dwelling
<b>CONDITION</b>	Excellent	<b>SECONDARY STRUCTURE</b>	Detached garage
<b>INTEGRITY</b>	Not altered	<b>NR SECOND</b>	NC
<b>CURRENT USE</b>	Domestic - single dwelling		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

New Traditional

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Permit

## **WALL MATERIAL (CURRENT)**

-

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

-

## **NO OF STORIES**

-

## **ROOF TYPE**

-

## **ROOF MATERIAL**

-

## **FOUNDATION**

-

## **PORCH**

-

## **WINDOW MATERIAL**

-

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

-

## **WINDOW CONFIGURATION**

-

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

-

## **ALTERATIONS**

-

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: FirstSt315(2)



Photo Id: first315



Photo Id: first315(2)

## HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

Nawrock, Douglas

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

-

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

## PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

## PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

## ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

JRB-06-0011

DATE

4/7/2006

BUILDING PERMIT DESCRIPTION

New single family residence

COST

\$425,830.00

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

-

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

-

OTHER SOURCES

-

HISTORIC INFO COMPILER

LR

VOLUNTEER

-



# Historic Libertyville

BEGINNING STREET NUMBER	316
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<b><u>LOCAL</u></b>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt316(1)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	-	<b>ZONING</b>	R-7
<b>GROUND FLOOR USE</b>	Residential	<b>NUMBER OF STORIES</b>	2
<b>UPPER FLOOR USE</b>	Residential	<b>PROPERTY INDEX NUMBER</b>	1116419002
<b>CURRENT OCCUPANT</b>	-		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	C	<b>NR ELIGIBLE?</b>	No
<b>WITHIN DISTRICT?</b>	No	<b>CRITERIA</b>	-
<b>NR LANDMARK?</b>	No	<b>ALTERNATE ADDRESS?</b>	-
<b>YEAR</b>	-		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	Building	<b>HISTORIC USE</b>	Domestic - single dwelling
<b>CONDITION</b>	Good	<b>SECONDARY STRUCTURE</b>	Detached garage
<b>INTEGRITY</b>	Minor alterations	<b>NR SECOND</b>	C
<b>CURRENT USE</b>	Domestic - single dwelling		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Gable Front Cottage

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Assessor

## **WALL MATERIAL (CURRENT)**

Aluminum/vinyl

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

Rectangular

## **NO OF STORIES**

1.5

## **ROOF TYPE**

Front Gable

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Parged

## **PORCH**

Full Front

## **WINDOW MATERIAL**

Wood

## **WINDOW MATERIAL 2**

Aluminum/vinyl

## **WINDOW TYPE**

Double hung & casement

## **WINDOW CONFIGURATION**

6/1; 1-light

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

Front gable roof; rectangular massing; hipped-roof porch (enclosed)

## **ALTERATIONS**

Front porch enclosed (post-1948); replacement windows in original openings (casement and fixed); replacement siding (1978)

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: FirstSt316(2)

## HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

## PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

## PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

## ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

# Historic Libertyville

BEGINNING STREET NUMBER	319
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<b><u>LOCAL</u></b>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt319(1)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	-	<b>ZONING</b>	R-7
<b>GROUND FLOOR USE</b>	Residential	<b>NUMBER OF STORIES</b>	1
<b>UPPER FLOOR USE</b>	N/A	<b>PROPERTY INDEX NUMBER</b>	1116415015
<b>CURRENT OCCUPANT</b>	-		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	C	<b>NR ELIGIBLE?</b>	No
<b>WITHIN DISTRICT?</b>	No	<b>CRITERIA</b>	-
<b>NR LANDMARK?</b>	No	<b>ALTERNATE ADDRESS?</b>	-
<b>YEAR</b>	-		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	Building	<b>HISTORIC USE</b>	Domestic - single dwelling
<b>CONDITION</b>	Good	<b>SECONDARY STRUCTURE</b>	Shed
<b>INTEGRITY</b>	minor alterations	<b>NR SECOND</b>	NC
<b>CURRENT USE</b>	Domestic - single dwelling		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Ranch

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Assessor

## **WALL MATERIAL (CURRENT)**

Aluminum/vinyl

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

Rectangular

## **NO OF STORIES**

1

## **ROOF TYPE**

Side Gable

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Concrete

## **PORCH**

-

## **WINDOW MATERIAL**

Wood

## **WINDOW MATERIAL 2**

Aluminum/vinyl

## **WINDOW TYPE**

Double Hung

## **WINDOW CONFIGURATION**

1/1

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

Shallow side gable roof and rectangular massing of original house; center entry; center wood window at north window bay on front facade

## **ALTERATIONS**

Aluminum siding (1980); 1-story rear addition (1966); replacement front door; replacement front stoop; most windows are 1/1 replacement windows

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: FirstSt319(2)



Photo Id: first319

## HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

## PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

## PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

## ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER



# Historic Libertyville

BEGINNING STREET NUMBER	321
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<b><u>LOCAL</u></b>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	Yes
CRITERIA	A



Photo Id: FirstSt321(1)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	-	<b>ZONING</b>	R-7
<b>GROUND FLOOR USE</b>	Residential	<b>NUMBER OF STORIES</b>	2
<b>UPPER FLOOR USE</b>	Residential	<b>PROPERTY INDEX NUMBER</b>	1116415014
<b>CURRENT OCCUPANT</b>	-		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	C	<b>NR ELIGIBLE?</b>	No
<b>WITHIN DISTRICT?</b>	No	<b>CRITERIA</b>	-
<b>NR LANDMARK?</b>	No	<b>ALTERNATE ADDRESS?</b>	-
<b>YEAR</b>	-		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	Building	<b>HISTORIC USE</b>	Domestic - single dwelling
<b>CONDITION</b>	Good	<b>SECONDARY STRUCTURE</b>	Detached garage
<b>INTEGRITY</b>	Minor alterations	<b>NR SECOND</b>	C
<b>CURRENT USE</b>	Domestic - single dwelling		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Gable Front

## **DETAILS**

Craftsman

## **OTHER YEAR**

-

## **DATE SOURCE**

Sanborn map (1924)

## **WALL MATERIAL (CURRENT)**

Wood - shingles

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

Rectangular

## **NO OF STORIES**

2

## **ROOF TYPE**

Front Gable

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Concrete-block

## **PORCH**

Full Front

## **WINDOW MATERIAL**

Wood

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

Double Hung

## **WINDOW CONFIGURATION**

1/1; 3/1

## **SIGNIFICANCE**

Well-preserved example of the Gable Front vernacular type, with Craftsman-style detailing.

## **HISTORIC FEATURES**

Front gable roof and rectangular massing; wood shingle siding; south end of porch structure is original (Sanborn map, 1924); historic 3/1 wood windows

## **ALTERATIONS**

Sanborn maps show north end of porch was built as an open porch some time between 1924 and 1933--enclosed later with 1/1 windows; aluminum soffits

## **ADDITIONAL PHOTOGRAPHS**



Photo Id: FirstSt321(3)



Photo Id: First321

## HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

## PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

## PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

## ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

# Historic Libertyville

BEGINNING STREET NUMBER	325
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<b><u>LOCAL</u></b>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt325

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	-	<b>ZONING</b>	R-7
<b>GROUND FLOOR USE</b>	Residential	<b>NUMBER OF STORIES</b>	2
<b>UPPER FLOOR USE</b>	Residential	<b>PROPERTY INDEX NUMBER</b>	1116415013
<b>CURRENT OCCUPANT</b>	-		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	NC	<b>NR ELIGIBLE?</b>	No
<b>WITHIN DISTRICT?</b>	No	<b>CRITERIA</b>	-
<b>NR LANDMARK?</b>	No	<b>ALTERNATE ADDRESS?</b>	-
<b>YEAR</b>	-		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	Building	<b>HISTORIC USE</b>	Domestic - single dwelling
<b>CONDITION</b>	Excellent	<b>SECONDARY STRUCTURE</b>	[attached garage]
<b>INTEGRITY</b>	Not altered	<b>NR SECOND</b>	-
<b>CURRENT USE</b>	Domestic - single dwelling		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

New Traditional - Tudor

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Permit

## **WALL MATERIAL (CURRENT)**

-

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

-

## **NO OF STORIES**

-

## **ROOF TYPE**

-

## **ROOF MATERIAL**

-

## **FOUNDATION**

-

## **PORCH**

-

## **WINDOW MATERIAL**

-

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

-

## **WINDOW CONFIGURATION**

-

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

-

## **ALTERATIONS**

-

**ADDITIONAL PHOTOGRAPHS**



Photo Id: first3252



Photo Id: first325

## HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

## PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

## PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

## ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER



# Historic Libertyville

BEGINNING STREET NUMBER	331-333
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<b><u>LOCAL</u></b>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt331-333(1)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	-	<b>ZONING</b>	R-7
<b>GROUND FLOOR USE</b>	Duplex	<b>NUMBER OF STORIES</b>	3
<b>UPPER FLOOR USE</b>	Duplex	<b>PROPERTY INDEX NUMBER</b>	1116415028 - 1116415029
<b>CURRENT OCCUPANT</b>	-		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	NC	<b>NR ELIGIBLE?</b>	No
<b>WITHIN DISTRICT?</b>	No	<b>CRITERIA</b>	-
<b>NR LANDMARK?</b>	No	<b>ALTERNATE ADDRESS?</b>	-
<b>YEAR</b>	-		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	Building	<b>HISTORIC USE</b>	Domestic - multiple dwelling
<b>CONDITION</b>	Good	<b>SECONDARY STRUCTURE</b>	[attached garage]
<b>INTEGRITY</b>	Not altered	<b>NR SECOND</b>	-
<b>CURRENT USE</b>	Domestic - multiple dwelling		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

No Style

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Permit

## **WALL MATERIAL (CURRENT)**

-

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

-

## **NO OF STORIES**

-

## **ROOF TYPE**

-

## **ROOF MATERIAL**

-

## **FOUNDATION**

-

## **PORCH**

-

## **WINDOW MATERIAL**

-

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

-

## **WINDOW CONFIGURATION**

-

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

-

## **ALTERATIONS**

-

**ADDITIONAL PHOTOGRAPHS**



Photo Id: First331333

## HISTORIC INFORMATION

**OLD ADDRESS (CITY DIR.YEAR)**

**BUILDING MOVED?**

**MOVED FROM**

**ORIGINAL OWNER**

**ORIGINAL ARCHITECT**

**ARCHITECT SOURCE**

**BUILDER**

**SURVEYOR**

**SURVEYOR ORGANIZATION**

**SURVEY DATE**

**SURVEY AREA**

## PERMIT/HISTORIC INFORMATION

**OLD ADDRESS**

**DATE OF CONSTRUCTION**

## PERMIT MOVING INFORMATION

**MOVING PERMIT #**

**DATE MOVED**

## ORIGINAL PERMIT INFORMATION

**BUILDING PERMIT #**

**DATE**

**BUILDING PERMIT DESCRIPTION**

**COST**

**ORIGINAL OWNER OCCUPIED?**

**EXTERIOR ALTERATION PERMITS**

**OTHER PERMIT INFORMATION**

**COA INFO**

**HISTORIC INFO**

**OTHER SOURCES**

**HISTORIC INFO COMPILER**

**VOLUNTEER**

# Historic Libertyville

BEGINNING STREET NUMBER	504
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	First Street
PIN	
<b><u>LOCAL</u></b>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: FirstSt504(1)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	-	<b>ZONING</b>	I-2
<b>GROUND FLOOR USE</b>	Commercial	<b>NUMBER OF STORIES</b>	1
<b>UPPER FLOOR USE</b>	N/A	<b>PROPERTY INDEX NUMBER</b>	1116408004
<b>CURRENT OCCUPANT</b>	-		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	NC	<b>NR ELIGIBLE?</b>	No
<b>WITHIN DISTRICT?</b>	No	<b>CRITERIA</b>	-
<b>NR LANDMARK?</b>	No	<b>ALTERNATE ADDRESS?</b>	-
<b>YEAR</b>	-		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	Building	<b>HISTORIC USE</b>	Industry/Processing/Extraction - Warehouse
<b>CONDITION</b>	Good	<b>SECONDARY STRUCTURE</b>	-
<b>INTEGRITY</b>	Major alterations and additiona	<b>NR SECOND</b>	-
<b>CURRENT USE</b>	Commerce/Trade		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

No Style

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Permit

## **WALL MATERIAL (CURRENT)**

Concrete block

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

Rectangular

## **NO OF STORIES**

1

## **ROOF TYPE**

Front Gable

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Concrete

## **PORCH**

-

## **WINDOW MATERIAL**

Aluminum/vinyl

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

Double Hung

## **WINDOW CONFIGURATION**

1/1

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

Broad gable roof

## **ALTERATIONS**

Gable roof replacing original flat roof; replacement windows in downsized openings; replacement front door; awning over entry; 1 story rear addition (1985)

**ADDITIONAL PHOTOGRAPHS**



Photo Id: First504

## HISTORIC INFORMATION

**OLD ADDRESS (CITY DIR.YEAR)**

-

**BUILDING MOVED?**

-

**MOVED FROM**

-

**ORIGINAL OWNER**

Ortseifen, A. J.

**ORIGINAL ARCHITECT**

-

**ARCHITECT SOURCE**

-

**BUILDER**

-

**SURVEYOR**

LR

**SURVEYOR ORGANIZATION**

Ramsey Historic Consultants

**SURVEY DATE**

May-June 2016

**SURVEY AREA**

Downtown Libertyville

## PERMIT/HISTORIC INFORMATION

**OLD ADDRESS**

-

**DATE OF CONSTRUCTION**

-

## PERMIT MOVING INFORMATION

**MOVING PERMIT #**

-

**DATE MOVED**

-

## ORIGINAL PERMIT INFORMATION

**BUILDING PERMIT #**

447

**DATE**

9/10/1952

**BUILDING PERMIT DESCRIPTION**

-

**COST**

-

**ORIGINAL OWNER OCCUPIED?**

-

**EXTERIOR ALTERATION PERMITS**

85-327 (1985)--addition (?--not clear on permit, \$30,000);

**OTHER PERMIT INFORMATION**

-

**COA INFO**

-

**HISTORIC INFO**

Building was occupied by Ace Welding Service--information on business on Illinois Digital Archive (provided by Libertyville-Mundelein Historical Society and Cook Memorial Public Library)-- "Historic photo of building on Illinois Digital Archives (in collection of Libertyville-Mundelein Historical Society and Cook Memorial Public Library)--This business offered general repairs on residential and industrial steel structures and ornamental iron. In addition, they manufactured new truck bodies and utility and boat trailers."

**OTHER SOURCES**

Historic photo of building on Illinois Digital Archives (in collection of Libertyville-Mundelein Historical Society and Cook Memorial Public Library)--  
<http://www.idaillinois.org/cdm/ref/collection/cookmemo11/id/1980>

**HISTORIC INFO COMPILER**

LR

**VOLUNTEER**

-



# Historic Libertyville

<b>BEGINNING STREET NUMBER</b>	510
<b>END STREET NUMBER</b>	-
<b>STREET # SUFFIX</b>	-
<b>STREET NAME</b>	First Street
<b>PIN</b>	
<b><u>LOCAL</u></b>	
<b>WITHIN LOCAL DISTRICT?</b>	No
<b>LOCAL DIST CONTRIB/NON-CONTRIB?</b>	NC
<b>LOCAL LANDMARK?</b>	No
<b>YEAR</b>	-
<b>LOCAL LANDMARK ELIGIBLE?</b>	No
<b>CRITERIA</b>	-



Photo Id: FirstSt510

## BUILDING DETAILS

<b>BUILDING NAME</b>	-	<b>ZONING</b>	I-2
<b>GROUND FLOOR USE</b>	Commercial	<b>NUMBER OF STORIES</b>	2
<b>UPPER FLOOR USE</b>	Commercial	<b>PROPERTY INDEX NUMBER</b>	1116408013
<b>CURRENT OCCUPANT</b>	-		

## NATIONAL REGISTER

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	NC	<b>NR ELIGIBLE?</b>	No
<b>WITHIN DISTRICT?</b>	No	<b>CRITERIA</b>	-
<b>NR LANDMARK?</b>	No	<b>ALTERNATE ADDRESS?</b>	-
<b>YEAR</b>	-		

## GENERAL INFORMATION

<b>CATEGORY</b>	Building	<b>HISTORIC USE</b>	Industry/Processing/Extraction
<b>CONDITION</b>	Good	<b>SECONDARY STRUCTURE</b>	-
<b>INTEGRITY</b>	Major alterations and additions	<b>NR SECOND</b>	-
<b>CURRENT USE</b>	Commerce/Trade		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

No Style

## **DETAILS**

-

## **OTHER YEAR**

-

## **DATE SOURCE**

Surveyor/Sanborn Maps

## **WALL MATERIAL (CURRENT)**

Concrete block

## **WALL MATERIAL 2 (CURRENT)**

Stucco

## **PLAN**

Rectangular

## **NO OF STORIES**

2

## **ROOF TYPE**

Front Gable

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Concrete-block

## **PORCH**

-

## **WINDOW MATERIAL**

Aluminum/vinyl

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

Double Hung

## **WINDOW CONFIGURATION**

1/1

## **SIGNIFICANCE**

-

## **HISTORIC FEATURES**

-

## **ALTERATIONS**

Multiple rear additions that are substantially larger than original building (last addition dates from 1984); front facade stuccoed; non-historic front entrance with awning; replacement windows in altered openings

**ADDITIONAL PHOTOGRAPHS**



Photo Id: First510

## HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

## PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

## PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

## ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

# Historic Libertyville

<b>BEGINNING STREET NUMBER</b>	518
<b>END STREET NUMBER</b>	-
<b>STREET # SUFFIX</b>	-
<b>STREET NAME</b>	First Street
<b>PIN</b>	
<b><u>LOCAL</u></b>	
<b>WITHIN LOCAL DISTRICT?</b>	No
<b>LOCAL DIST CONTRIB/NON-CONTRIB?</b>	C
<b>LOCAL LANDMARK?</b>	No
<b>YEAR</b>	-
<b>LOCAL LANDMARK ELIGIBLE?</b>	Potentially Eligible
<b>CRITERIA</b>	A



Photo Id: FirstSt518(2)

## **BUILDING DETAILS**

<b>BUILDING NAME</b>	-	<b>ZONING</b>	R-7
<b>GROUND FLOOR USE</b>	Residential	<b>NUMBER OF STORIES</b>	2
<b>UPPER FLOOR USE</b>	Residential	<b>PROPERTY INDEX NUMBER</b>	1116408002
<b>CURRENT OCCUPANT</b>	-		

## **NATIONAL REGISTER**

<b>NR DISTRICT CONTRIB/NON-CONTRIB</b>	C	<b>NR ELIGIBLE?</b>	No
<b>WITHIN DISTRICT?</b>	No	<b>CRITERIA</b>	-
<b>NR LANDMARK?</b>	No	<b>ALTERNATE ADDRESS?</b>	-
<b>YEAR</b>	-		

## **GENERAL INFORMATION**

<b>CATEGORY</b>	Building	<b>HISTORIC USE</b>	Domestic - single dwelling
<b>CONDITION</b>	Good	<b>SECONDARY STRUCTURE</b>	Detached garage
<b>INTEGRITY</b>	Minor alterations and additions	<b>NR SECOND</b>	NC
<b>CURRENT USE</b>	Domestic - single dwelling		

# **ARCHITECTURAL DESCRIPTION**

## **ARCHITECTURAL CLASSIFICATION**

Italianate

## **DETAILS**

-

## **OTHER YEAR**

2002

## **DATE SOURCE**

Surveyor/permit

## **WALL MATERIAL (CURRENT)**

Wood

## **WALL MATERIAL 2 (CURRENT)**

-

## **PLAN**

Rectangular

## **NO OF STORIES**

2

## **ROOF TYPE**

Hipped

## **ROOF MATERIAL**

Asphalt - shingle

## **FOUNDATION**

Concrete

## **PORCH**

Front entry

## **WINDOW MATERIAL**

Wood

## **WINDOW MATERIAL 2**

-

## **WINDOW TYPE**

Double Hung

## **WINDOW CONFIGURATION**

1/1

## **SIGNIFICANCE**

Fine example Italianate residential architecture in the village, with characteristic bracketed cornice and classical wood window surrounds. The enclosed front porch and open entry porch on the north facade are non-historic alterations.

## **HISTORIC FEATURES**

Shallow hipped roof; wood cornice with scrolled brackets; classical wood window surrounds

## **ALTERATIONS**

Front porch addition (not historic); original north side sun porch removed and replaced with small entry porch (not historic)

**ADDITIONAL PHOTOGRAPHS**



Photo Id: FirstSt518(3)



Photo Id: First518



Photo Id: First518(2)

## HISTORIC INFORMATION

**OLD ADDRESS (CITY DIR.YEAR)**

-

**BUILDING MOVED?**

Yes

**MOVED FROM**

Unknown

**ORIGINAL OWNER**

-

**ORIGINAL ARCHITECT**

-

**ARCHITECT SOURCE**

-

**BUILDER**

-

**SURVEYOR**

LR

**SURVEYOR ORGANIZATION**

Ramsey Historic Consultants

**SURVEY DATE**

May-June 2016

**SURVEY AREA**

Downtown Libertyville

## PERMIT/HISTORIC INFORMATION

**OLD ADDRESS**

-

**DATE OF CONSTRUCTION**

-

## PERMIT MOVING INFORMATION

**MOVING PERMIT #**

-

**DATE MOVED**

-

## ORIGINAL PERMIT INFORMATION

**BUILDING PERMIT #**

-

**DATE**

-

**BUILDING PERMIT DESCRIPTION**

-

**COST**

-

**ORIGINAL OWNER OCCUPIED?**

-

**EXTERIOR ALTERATION PERMITS**

#00-20A (7/15/2002)--detached garage; porch alterations and fence; 85-224 (7/31/1985)--construct outside stair; 77-484 (8/4/1977)--addition (\$15,000)

**OTHER PERMIT INFORMATION**

-

**COA INFO**

-

**HISTORIC INFO**

Based on Sanborn maps, it appears that the house was moved from another location some time after 1948. A 1951 permit for a one-story single-family residence was found in the village building files, but the lot number doesn't match that of the subject house. No moving permit was found.

**OTHER SOURCES**

Sanborn Maps--1924, 1933, 1948 IHSS photograph (mid-1970s)

**HISTORIC INFO COMPILER**

LR

**VOLUNTEER**

-