

Historic Libertyville

BEGINNING STREET NUMBER	136
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Newberry Avenue
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	Potentially Eligible
CRITERIA	A



Photo Id: NewberryAve136(1)

BUILDING DETAILS

BUILDING NAME	-	ZONING	R-7
GROUND FLOOR USE	Residential	NUMBER OF STORIES	1
UPPER FLOOR USE	N/A	PROPERTY INDEX NUMBER	1116403006
CURRENT OCCUPANT	-		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	C	NR ELIGIBLE?	No
WITHIN DISTRICT?	No	CRITERIA	-
NR LANDMARK?	No	ALTERNATE ADDRESS?	-
YEAR	-		

GENERAL INFORMATION

CATEGORY	Building	HISTORIC USE	Domestic - single dwelling
CONDITION	Good	SECONDARY STRUCTURE	Detached garage
INTEGRITY	Minor alterations	NR SECOND	NC
CURRENT USE	Domestic - single dwelling		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Craftsman Bungalow

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

Stucco

PLAN

Irregular

NO OF STORIES

1.5

ROOF TYPE

Side Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Concrete-block

PORCH

Corner entry

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

Aluminum/vinyl

WINDOW TYPE

Double hung, casement & fixed

WINDOW CONFIGURATION

1/1; multi-light; multi-light/1

SIGNIFICANCE

Despite some alterations, this Craftsman Bungalow may be eligible for local landmark designation.

HISTORIC FEATURES

Side gable roof with L brackets under eaves; front gable bay with battered corners, decorative half timbering; east side oriel window bay; corner entry porch with battered square columns; gable front dormer

ALTERATIONS

Replacement siding on sections of exterior; front porch enclosed; alterations to rear porch (replaced 1956, alterations 1970)

ADDITIONAL PHOTOGRAPHS



Photo Id: NewberryAve136(2)



Photo Id: Newberry136

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

No permit # (5/29/1970)--repairing front and rear steps, new decking and rails on rear porch; 1417 (4/28/1956)--new back porch replacing present porch;

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	<input type="text" value="140"/>
END STREET NUMBER	<input type="text" value="-"/>
STREET # SUFFIX	<input type="text" value="-"/>
STREET NAME	<input type="text" value="Newberry Avenue"/>
PIN	<input type="text"/>
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	<input type="text" value="No"/>
LOCAL DIST CONTRIB/NON-CONTRIB?	<input type="text" value="C"/>
LOCAL LANDMARK?	<input type="text" value="No"/>
YEAR	<input type="text" value="-"/>
LOCAL LANDMARK ELIGIBLE?	<input type="text" value="No"/>
CRITERIA	<input type="text" value="-"/>



Photo Id: NewberryAve140

BUILDING DETAILS

BUILDING NAME	<input type="text" value="-"/>	ZONING	<input type="text" value="R-7"/>
GROUND FLOOR USE	<input type="text" value="Residential"/>	NUMBER OF STORIES	<input type="text" value="2"/>
UPPER FLOOR USE	<input type="text" value="Residential"/>	PROPERTY INDEX NUMBER	<input type="text" value="1116403007"/>
CURRENT OCCUPANT	<input type="text" value="-"/>		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	<input type="text" value="C"/>	NR ELIGIBLE?	<input type="text" value="No"/>
WITHIN DISTRICT?	<input type="text" value="No"/>	CRITERIA	<input type="text" value="-"/>
NR LANDMARK?	<input type="text" value="No"/>	ALTERNATE ADDRESS?	<input type="text" value="-"/>
YEAR	<input type="text" value="-"/>		

GENERAL INFORMATION

CATEGORY	<input type="text" value="Building"/>	HISTORIC USE	<input type="text" value="Domestic - multiple dwelling"/>
CONDITION	<input type="text" value="Good"/>	SECONDARY STRUCTURE	<input type="text" value="-"/>
INTEGRITY	<input type="text" value="Minor alterations"/>	NR SECOND	<input type="text" value="-"/>
CURRENT USE	<input type="text" value="Domestic - multiple dwelling"/>		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Contemporary

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Permit

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

Brick

PLAN

Rectangular

NO OF STORIES

2

ROOF TYPE

Hipped

ROOF MATERIAL

Not Visible

FOUNDATION

Concrete

PORCH

-

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double hung & fixed

WINDOW CONFIGURATION

1/1; 1-light

SIGNIFICANCE

-

HISTORIC FEATURES

-

ALTERATIONS

Replacement siding; replacement front door

ADDITIONAL PHOTOGRAPHS



Photo Id: Newberry140

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

Meyer, Robert C. & Lincoln

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

Meyer, Robert C. & Lincoln

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

2801

DATE

2/2/1961

BUILDING PERMIT DESCRIPTION

two-family residence

COST

\$20,343.00

ORIGINAL OWNER OCCUPIED?

-

EXTERIOR ALTERATION PERMITS

-

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

-

OTHER SOURCES

-

HISTORIC INFO COMPILER

LR

VOLUNTEER

-

Historic Libertyville

BEGINNING STREET NUMBER	<input type="text" value="143"/>
END STREET NUMBER	<input type="text" value="-"/>
STREET # SUFFIX	<input type="text" value="-"/>
STREET NAME	<input type="text" value="Newberry Avenue"/>
PIN	<input type="text"/>
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	<input type="text" value="No"/>
LOCAL DIST CONTRIB/NON-CONTRIB?	<input type="text" value="C"/>
LOCAL LANDMARK?	<input type="text" value="No"/>
YEAR	<input type="text" value="-"/>
LOCAL LANDMARK ELIGIBLE?	<input type="text" value="No"/>
CRITERIA	<input type="text" value="-"/>



Photo Id: NewberryAve143(1)

BUILDING DETAILS

BUILDING NAME	<input type="text" value="-"/>	ZONING	<input type="text" value="R-7"/>
GROUND FLOOR USE	<input type="text" value="Residential"/>	NUMBER OF STORIES	<input type="text" value="2"/>
UPPER FLOOR USE	<input type="text" value="Residential"/>	PROPERTY INDEX NUMBER	<input type="text" value="1116404004"/>
CURRENT OCCUPANT	<input type="text" value="-"/>		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	<input type="text" value="C"/>	NR ELIGIBLE?	<input type="text" value="No"/>
WITHIN DISTRICT?	<input type="text" value="No"/>	CRITERIA	<input type="text" value="-"/>
NR LANDMARK?	<input type="text" value="No"/>	ALTERNATE ADDRESS?	<input type="text" value="-"/>
YEAR	<input type="text" value="-"/>		

GENERAL INFORMATION

CATEGORY	<input type="text" value="Building"/>	HISTORIC USE	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="Good"/>	SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>
INTEGRITY	<input type="text" value="Moderate alterations"/>	NR SECOND	<input type="text" value="NC"/>
CURRENT USE	<input type="text" value="Domestic - single dwelling"/>		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Gable Front

DETAILS

-

OTHER YEAR

1993-5

DATE SOURCE

Owner (House History)/permit

WALL MATERIAL (CURRENT)

Wood

WALL MATERIAL 2 (CURRENT)

-

PLAN

Irregular

NO OF STORIES

2.5

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Brick

PORCH

Full Front

WINDOW MATERIAL

Clad wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

1/1; 1-light

SIGNIFICANCE

-

HISTORIC FEATURES

Front gable roof; hipped full-front porch structure (historic, but not original-see 1912 and 1924 Sanborn maps); two-story west gable bay (altered)

ALTERATIONS

Wood siding is replacement; replacement windows in original openings; replacement railings and columns on front porch; two-story rear and west addition (1993); replacement front door

ADDITIONAL PHOTOGRAPHS



Photo Id: NewberryAve143(2)



Photo Id: Newberry143

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	146
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Newberry Avenue
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: NewberryAve146(1)

BUILDING DETAILS

BUILDING NAME	-	ZONING	R-7
GROUND FLOOR USE	Residential	NUMBER OF STORIES	2
UPPER FLOOR USE	Residential	PROPERTY INDEX NUMBER	1116403008
CURRENT OCCUPANT	-		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	C	NR ELIGIBLE?	No
WITHIN DISTRICT?	No	CRITERIA	-
NR LANDMARK?	No	ALTERNATE ADDRESS?	-
YEAR	-		

GENERAL INFORMATION

CATEGORY	Building	HISTORIC USE	Domestic - single dwelling
CONDITION	Good	SECONDARY STRUCTURE	Detached garage
INTEGRITY	Moderate alterations	NR SECOND	NC
CURRENT USE	Domestic - single dwelling		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Gable Front

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Sanborn maps (1907, 1912)

WALL MATERIAL (CURRENT)

Hardie board

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Parged

PORCH

Full Front

WINDOW MATERIAL

Aluminum/vinyl

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

6/1; 4/1

SIGNIFICANCE

-

HISTORIC FEATURES

Front gable roof; east-side gable bay; front porch structure with hipped roof

ALTERATIONS

Exterior remodeling in 2012--replacement siding; replacement windows in original openings; replacement porch columns and step railings; rear porch enclosed (post-1948)

ADDITIONAL PHOTOGRAPHS



Photo Id: NewberryAve146(3)



Photo Id: Newberry146

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	149
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Newberry Avenue
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: NewberryAve149(1)

BUILDING DETAILS

BUILDING NAME	-	ZONING	R-7
GROUND FLOOR USE	Residential	NUMBER OF STORIES	2
UPPER FLOOR USE	Residential	PROPERTY INDEX NUMBER	1116404006
CURRENT OCCUPANT	-		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NC	NR ELIGIBLE?	No
WITHIN DISTRICT?	No	CRITERIA	-
NR LANDMARK?	No	ALTERNATE ADDRESS?	-
YEAR	-		

GENERAL INFORMATION

CATEGORY	Building	HISTORIC USE	Domestic - single dwelling
CONDITION	Excellent	SECONDARY STRUCTURE	Detached garage
INTEGRITY	Not altered	NR SECOND	NC
CURRENT USE	Domestic - single dwelling		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

New Traditional

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Permit/Assessor

WALL MATERIAL (CURRENT)

-

WALL MATERIAL 2 (CURRENT)

-

PLAN

-

NO OF STORIES

-

ROOF TYPE

-

ROOF MATERIAL

-

FOUNDATION

-

PORCH

-

WINDOW MATERIAL

-

WINDOW MATERIAL 2

-

WINDOW TYPE

-

WINDOW CONFIGURATION

-

SIGNIFICANCE

-

HISTORIC FEATURES

-

ALTERATIONS

-

ADDITIONAL PHOTOGRAPHS



Photo Id: NewberryAve149(2)



Photo Id: Newberry149

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	150-152
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Newberry Avenue
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: NewberryAve150

BUILDING DETAILS

BUILDING NAME	-
GROUND FLOOR USE	Residential
UPPER FLOOR USE	N/A
CURRENT OCCUPANT	-

ZONING	R-7
NUMBER OF STORIES	1
PROPERTY INDEX NUMBER	-

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	C
WITHIN DISTRICT?	No
NR LANDMARK?	No
YEAR	-

NR ELIGIBLE?	No
CRITERIA	-
ALTERNATE ADDRESS?	-

GENERAL INFORMATION

CATEGORY	Building
CONDITION	Good
INTEGRITY	Minor alterations
CURRENT USE	Domestic - single dwelling

HISTORIC USE	Domestic - single dwelling
SECONDARY STRUCTURE	-
NR SECOND	-

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Minimal Traditional

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Surveyor/Sanborn Maps

WALL MATERIAL (CURRENT)

Brick

WALL MATERIAL 2 (CURRENT)

Stone

PLAN

Rectangular

NO OF STORIES

1

ROOF TYPE

Side Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Concrete

PORCH

-

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

-

WINDOW TYPE

Casement & fixed

WINDOW CONFIGURATION

8-light; 1-light

SIGNIFICANCE

-

HISTORIC FEATURES

Materials (siding, windows, door) all appear original; stone chimney and front planter box

ALTERATIONS

One casement windows on front facade bricked in

ADDITIONAL PHOTOGRAPHS



Photo Id: NewberryAve150(2)

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	155
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Newberry Avenue
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: NewberryAve155(1)

BUILDING DETAILS

BUILDING NAME	-	ZONING	R-7
GROUND FLOOR USE	Residential	NUMBER OF STORIES	2
UPPER FLOOR USE	Residential	PROPERTY INDEX NUMBER	1116404007
CURRENT OCCUPANT	-		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NC	NR ELIGIBLE?	No
WITHIN DISTRICT?	No	CRITERIA	-
NR LANDMARK?	No	ALTERNATE ADDRESS?	-
YEAR	-		

GENERAL INFORMATION

CATEGORY	Building	HISTORIC USE	Domestic - single dwelling
CONDITION	Excellent	SECONDARY STRUCTURE	Detached garage
INTEGRITY	Not altered	NR SECOND	NC
CURRENT USE	Domestic - single dwelling		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

New Traditional

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Permit/Assessor

WALL MATERIAL (CURRENT)

-

WALL MATERIAL 2 (CURRENT)

-

PLAN

-

NO OF STORIES

-

ROOF TYPE

-

ROOF MATERIAL

-

FOUNDATION

-

PORCH

-

WINDOW MATERIAL

-

WINDOW MATERIAL 2

-

WINDOW TYPE

-

WINDOW CONFIGURATION

-

SIGNIFICANCE

-

HISTORIC FEATURES

-

ALTERATIONS

-

ADDITIONAL PHOTOGRAPHS



Photo Id: NewberryAve155(2)



Photo Id: Newberry155

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	<input type="text" value="158"/>
END STREET NUMBER	<input type="text" value="-"/>
STREET # SUFFIX	<input type="text" value="-"/>
STREET NAME	<input type="text" value="Newberry Avenue"/>
PIN	<input type="text"/>
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	<input type="text" value="No"/>
LOCAL DIST CONTRIB/NON-CONTRIB?	<input type="text" value="NC"/>
LOCAL LANDMARK?	<input type="text" value="No"/>
YEAR	<input type="text" value="-"/>
LOCAL LANDMARK ELIGIBLE?	<input type="text" value="No"/>
CRITERIA	<input type="text" value="-"/>



Photo Id: NewberryAve158(1)

BUILDING DETAILS

BUILDING NAME	<input type="text" value="-"/>	ZONING	<input type="text" value="R-7"/>
GROUND FLOOR USE	<input type="text" value="Residential"/>	NUMBER OF STORIES	<input type="text" value="2"/>
UPPER FLOOR USE	<input type="text" value="Residential"/>	PROPERTY INDEX NUMBER	<input type="text" value="1116403022"/>
CURRENT OCCUPANT	<input type="text" value="-"/>		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	<input type="text" value="NC"/>	NR ELIGIBLE?	<input type="text" value="No"/>
WITHIN DISTRICT?	<input type="text" value="No"/>	CRITERIA	<input type="text" value="-"/>
NR LANDMARK?	<input type="text" value="No"/>	ALTERNATE ADDRESS?	<input type="text" value="-"/>
YEAR	<input type="text" value="-"/>		

GENERAL INFORMATION

CATEGORY	<input type="text" value="Building"/>	HISTORIC USE	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="Good"/>	SECONDARY STRUCTURE	<input type="text" value="-"/>
INTEGRITY	<input type="text" value="Major alterations and additions"/>	NR SECOND	<input type="text" value="-"/>
CURRENT USE	<input type="text" value="Domestic - single dwelling"/>		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

American Foursquare (altered)

DETAILS

-

OTHER YEAR

1986 (addition)

DATE SOURCE

Sanborn/surveyor/permit (addition)

WALL MATERIAL (CURRENT)

Wood

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular

NO OF STORIES

2

ROOF TYPE

Hipped

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Concrete

PORCH

Full Front

WINDOW MATERIAL

Aluminum/vinyl

WINDOW MATERIAL 2

-

WINDOW TYPE

Double hung & casement

WINDOW CONFIGURATION

1/1; 1-light

SIGNIFICANCE

-

HISTORIC FEATURES

Historic section of house at east

ALTERATIONS

Original massing and roofline of house obscured by large, 2-story west side addition built in 1986; original porch removed and replaced with new enclosed porch; replacement siding; replacement windows in original openings

ADDITIONAL PHOTOGRAPHS



Photo Id: NewberryAve119

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	<input type="text" value="159"/>
END STREET NUMBER	<input type="text" value="-"/>
STREET # SUFFIX	<input type="text" value="-"/>
STREET NAME	<input type="text" value="Newberry Avenue"/>
PIN	<input type="text"/>
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	<input type="text" value="No"/>
LOCAL DIST CONTRIB/NON-CONTRIB?	<input type="text" value="NC"/>
LOCAL LANDMARK?	<input type="text" value="No"/>
YEAR	<input type="text" value="-"/>
LOCAL LANDMARK ELIGIBLE?	<input type="text" value="No"/>
CRITERIA	<input type="text" value="-"/>



Photo Id: NewberryAve159(1)

BUILDING DETAILS

BUILDING NAME	<input type="text" value="-"/>	ZONING	<input type="text" value="R-7"/>
GROUND FLOOR USE	<input type="text" value="Residential"/>	NUMBER OF STORIES	<input type="text" value="2"/>
UPPER FLOOR USE	<input type="text" value="Residential"/>	PROPERTY INDEX NUMBER	<input type="text" value="1116404008"/>
CURRENT OCCUPANT	<input type="text" value="-"/>		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	<input type="text" value="NC"/>	NR ELIGIBLE?	<input type="text" value="No"/>
WITHIN DISTRICT?	<input type="text" value="No"/>	CRITERIA	<input type="text" value="-"/>
NR LANDMARK?	<input type="text" value="No"/>	ALTERNATE ADDRESS?	<input type="text" value="-"/>
YEAR	<input type="text" value="-"/>		

GENERAL INFORMATION

CATEGORY	<input type="text" value="Building"/>	HISTORIC USE	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="Good"/>	SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>
INTEGRITY	<input type="text" value="Major alterations and additions"/>	NR SECOND	<input type="text" value="NC"/>
CURRENT USE	<input type="text" value="Domestic - single dwelling"/>		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Craftsman Bungalow (altered)

DETAILS

-

OTHER YEAR

1997 (2nd story addition)

DATE SOURCE

Surveyor/Sanborn Map/permit

WALL MATERIAL (CURRENT)

Wood - shingles

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular

NO OF STORIES

2

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Parged

PORCH

Corner entry

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

Aluminum/vinyl

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

3/1; 6/1

SIGNIFICANCE

-

HISTORIC FEATURES

Historic 3/1 wood windows on first story; inset corner porch (enclosed)

ALTERATIONS

Second story is non-historic addition (see 1948 Sanborn map); replacement siding

ADDITIONAL PHOTOGRAPHS



Photo Id: NewberryAve159(2)



Photo Id: Newberry159

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	163
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	Newberry Avenue
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	Yes
CRITERIA	A



Photo Id: NewberryAve163(1)

BUILDING DETAILS

BUILDING NAME	-	ZONING	R-7
GROUND FLOOR USE	Residential	NUMBER OF STORIES	2
UPPER FLOOR USE	Residential	PROPERTY INDEX NUMBER	1116404009
CURRENT OCCUPANT	-		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	C	NR ELIGIBLE?	No
WITHIN DISTRICT?	No	CRITERIA	-
NR LANDMARK?	No	ALTERNATE ADDRESS?	-
YEAR	-		

GENERAL INFORMATION

CATEGORY	Building	HISTORIC USE	Domestic - single dwelling
CONDITION	Good	SECONDARY STRUCTURE	Detached garage
INTEGRITY	Minor alterations	NR SECOND	NC
CURRENT USE	Domestic - single dwelling		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Tudor Revival

DETAILS

Craftsman

OTHER YEAR

-

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Wood - shingles

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular

NO OF STORIES

2.5

ROOF TYPE

Side Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Brick & concrete

PORCH

-

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

Aluminum/vinyl

WINDOW TYPE

Double hung & casement

WINDOW CONFIGURATION

6/1; 6-light

SIGNIFICANCE

Charming c. 1930 Tudor Revival cottage, with characteristic asymmetrical front bay and round-arch entry.

HISTORIC FEATURES

Side gable roof with cornice returns; steeply-pitched front gable entry bay; round-arch door opening; historic wood windows; east end chimney; secondary entry with canopy on east facade

ALTERATIONS

Replacement front door; rear porch enclosed (1955)

ADDITIONAL PHOTOGRAPHS



Photo Id: NewberryAve163(2)



Photo Id: Newberry163

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER