

Historic Libertyville

BEGINNING STREET NUMBER	222-224
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	E. Church Street
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ChurchStE222-224(1)

BUILDING DETAILS

BUILDING NAME	-	ZONING	R-8
GROUND FLOOR USE	Duplex	NUMBER OF STORIES	2
UPPER FLOOR USE	Duplex	PROPERTY INDEX NUMBER	1116411037 (222), 1116411038 (224)
CURRENT OCCUPANT	-		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NC	NR ELIGIBLE?	No
WITHIN DISTRICT?	No	CRITERIA	-
NR LANDMARK?	No	ALTERNATE ADDRESS?	-
YEAR	-		

GENERAL INFORMATION

CATEGORY	Building	HISTORIC USE	Domestic - multiple dwelling
CONDITION	Excellent	SECONDARY STRUCTURE	[attached garage]
INTEGRITY	Not altered	NR SECOND	-
CURRENT USE	Domestic - multiple dwelling		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

New Traditional

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

-

WALL MATERIAL 2 (CURRENT)

-

PLAN

-

NO OF STORIES

-

ROOF TYPE

-

ROOF MATERIAL

-

FOUNDATION

-

PORCH

-

WINDOW MATERIAL

-

WINDOW MATERIAL 2

-

WINDOW TYPE

-

WINDOW CONFIGURATION

-

SIGNIFICANCE

-

HISTORIC FEATURES

-

ALTERATIONS

-

ADDITIONAL PHOTOGRAPHS



Photo Id: EChurch222224

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	223
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	E. Church Street
PIN	
LOCAL	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ChurchStE223(2)

BUILDING DETAILS

BUILDING NAME	-	ZONING	R-7
GROUND FLOOR USE	Residence	NUMBER OF STORIES	2
UPPER FLOOR USE	Residential	PROPERTY INDEX NUMBER	1116415004
CURRENT OCCUPANT	-		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	C	NR ELIGIBLE?	No
WITHIN DISTRICT?	No	CRITERIA	-
NR LANDMARK?	No	ALTERNATE ADDRESS?	-
YEAR	-		

GENERAL INFORMATION

CATEGORY	Building	HISTORIC USE	Domestic - single dwelling
CONDITION	Fair	SECONDARY STRUCTURE	Detached garage
INTEGRITY	Moderate alterations and additions	NR SECOND	NC
CURRENT USE	Domestic - single dwelling		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Gable Front

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Brick

PORCH

Full Front

WINDOW MATERIAL

Aluminum/vinyl

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

1/1

SIGNIFICANCE

-

HISTORIC FEATURES

Front gable roof and rectangular massing; full front hipped-roof porch structure

ALTERATIONS

Replacement siding; replacement windows in original openings; replacement columns on front porch; 1-story rear addition; fixed shutters

ADDITIONAL PHOTOGRAPHS



Photo Id: ChurchStE223(3)



Photo Id: EChurch223

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	<input type="text" value="225"/>
END STREET NUMBER	<input type="text" value="-"/>
STREET # SUFFIX	<input type="text" value="-"/>
STREET NAME	<input type="text" value="E. Church Street"/>
PIN	<input type="text"/>
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	<input type="text" value="No"/>
LOCAL DIST CONTRIB/NON-CONTRIB?	<input type="text" value="NC"/>
LOCAL LANDMARK?	<input type="text" value="No"/>
YEAR	<input type="text" value="-"/>
LOCAL LANDMARK ELIGIBLE?	<input type="text" value="No"/>
CRITERIA	<input type="text" value="-"/>



Photo Id: ChurchStE225(2)

BUILDING DETAILS

BUILDING NAME	<input type="text" value="-"/>	ZONING	<input type="text" value="R-7"/>
GROUND FLOOR USE	<input type="text" value="Residence"/>	NUMBER OF STORIES	<input type="text" value="1.5"/>
UPPER FLOOR USE	<input type="text" value="Residential"/>	PROPERTY INDEX NUMBER	<input type="text" value="1116415005"/>
CURRENT OCCUPANT	<input type="text" value="-"/>		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	<input type="text" value="NC"/>	NR ELIGIBLE?	<input type="text" value="No"/>
WITHIN DISTRICT?	<input type="text" value="No"/>	CRITERIA	<input type="text" value="-"/>
NR LANDMARK?	<input type="text" value="No"/>	ALTERNATE ADDRESS?	<input type="text" value="-"/>
YEAR	<input type="text" value="-"/>		

GENERAL INFORMATION

CATEGORY	<input type="text" value="Building"/>	HISTORIC USE	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="Good"/>	SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>
INTEGRITY	<input type="text" value="Major alterations and/or additions"/>	NR SECOND	<input type="text" value="NC"/>
CURRENT USE	<input type="text" value="Domestic - single dwelling"/>		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Gable Front

DETAILS

-

OTHER YEAR

1925 (c.); 1998

DATE SOURCE

Assessor; surveyor; permit

WALL MATERIAL (CURRENT)

Wood

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular

NO OF STORIES

1.5

ROOF TYPE

Front Gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Brick

PORCH

-

WINDOW MATERIAL

-

WINDOW MATERIAL 2

Aluminum/vinyl

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

-

SIGNIFICANCE

-

HISTORIC FEATURES

Rectangular massing; corner porch structure added c. 1925

ALTERATIONS

Major renovation in 1998--roof raised and pitch altered, and dormers added; replacement windows in original openings; round arch window added on front gable wall; replacement front porch supports and railing

ADDITIONAL PHOTOGRAPHS



Photo Id: ChurchStE225(3)



Photo Id: EChurch225

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	226-228
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	E. Church Street
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: EChurch226228

BUILDING DETAILS

BUILDING NAME	-	ZONING	R-8
GROUND FLOOR USE	Duplex	NUMBER OF STORIES	2
UPPER FLOOR USE	Duplex	PROPERTY INDEX NUMBER	1116411041 (226), 1116411042 (228)
CURRENT OCCUPANT	-		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NC	NR ELIGIBLE?	No
WITHIN DISTRICT?	No	CRITERIA	-
NR LANDMARK?	No	ALTERNATE ADDRESS?	-
YEAR	-		

GENERAL INFORMATION

CATEGORY	Building	HISTORIC USE	Domestic - multiple dwelling
CONDITION	Excellent	SECONDARY STRUCTURE	[attached garage]
INTEGRITY	Not altered	NR SECOND	-
CURRENT USE	Domestic - multiple dwelling		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

New Traditional

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

-

WALL MATERIAL 2 (CURRENT)

-

PLAN

-

NO OF STORIES

-

ROOF TYPE

-

ROOF MATERIAL

-

FOUNDATION

-

PORCH

-

WINDOW MATERIAL

-

WINDOW MATERIAL 2

-

WINDOW TYPE

-

WINDOW CONFIGURATION

-

SIGNIFICANCE

-

HISTORIC FEATURES

-

ALTERATIONS

-

ADDITIONAL PHOTOGRAPHS



Photo Id: ChurchStE226-228

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	<input type="text" value="232"/>
END STREET NUMBER	<input type="text" value="-"/>
STREET # SUFFIX	<input type="text" value="-"/>
STREET NAME	<input type="text" value="E. Church Street"/>
PIN	<input type="text"/>
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	<input type="text" value="No"/>
LOCAL DIST CONTRIB/NON-CONTRIB?	<input type="text" value="NC"/>
LOCAL LANDMARK?	<input type="text" value="No"/>
YEAR	<input type="text" value="-"/>
LOCAL LANDMARK ELIGIBLE?	<input type="text" value="No"/>
CRITERIA	<input type="text" value="-"/>



Photo Id: EChurch232

BUILDING DETAILS

BUILDING NAME	<input type="text" value="-"/>	ZONING	<input type="text" value="R-8"/>
GROUND FLOOR USE	<input type="text" value="Residential Apartments"/>	NUMBER OF STORIES	<input type="text" value="2"/>
UPPER FLOOR USE	<input type="text" value="Residential Apartments"/>	PROPERTY INDEX NUMBER	<input type="text" value="1116411043"/>
CURRENT OCCUPANT	<input type="text" value="-"/>		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	<input type="text" value="NC"/>	NR ELIGIBLE?	<input type="text" value="No"/>
WITHIN DISTRICT?	<input type="text" value="No"/>	CRITERIA	<input type="text" value="-"/>
NR LANDMARK?	<input type="text" value="No"/>	ALTERNATE ADDRESS?	<input type="text" value="-"/>
YEAR	<input type="text" value="-"/>		

GENERAL INFORMATION

CATEGORY	<input type="text" value="Building"/>	HISTORIC USE	<input type="text" value="Domestic - multiple dwelling"/>
CONDITION	<input type="text" value="Good"/>	SECONDARY STRUCTURE	<input type="text" value="-"/>
INTEGRITY	<input type="text" value="Minor alterations"/>	NR SECOND	<input type="text" value="-"/>
CURRENT USE	<input type="text" value="Domestic - multiple dwelling"/>		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Mansard

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Demolition Permit for SFR on site

WALL MATERIAL (CURRENT)

-

WALL MATERIAL 2 (CURRENT)

-

PLAN

-

NO OF STORIES

-

ROOF TYPE

-

ROOF MATERIAL

-

FOUNDATION

-

PORCH

-

WINDOW MATERIAL

-

WINDOW MATERIAL 2

-

WINDOW TYPE

-

WINDOW CONFIGURATION

-

SIGNIFICANCE

-

HISTORIC FEATURES

-

ALTERATIONS

-

ADDITIONAL PHOTOGRAPHS



Photo Id: ChurchStE232(1)

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	305
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	E. Church Street
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ChurchStE305(1)

BUILDING DETAILS

BUILDING NAME	-	ZONING	R-7
GROUND FLOOR USE	Residential	NUMBER OF STORIES	2
UPPER FLOOR USE	Residential	PROPERTY INDEX NUMBER	1116416017
CURRENT OCCUPANT	-		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NC	NR ELIGIBLE?	No
WITHIN DISTRICT?	No	CRITERIA	-
NR LANDMARK?	No	ALTERNATE ADDRESS?	-
YEAR	-		

GENERAL INFORMATION

CATEGORY	Building	HISTORIC USE	Domestic - single dwelling
CONDITION	Excellent	SECONDARY STRUCTURE	[attached garage]
INTEGRITY	Not altered	NR SECOND	-
CURRENT USE	Domestic - single dwelling		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

New Traditional

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Permit

WALL MATERIAL (CURRENT)

-

WALL MATERIAL 2 (CURRENT)

-

PLAN

-

NO OF STORIES

-

ROOF TYPE

-

ROOF MATERIAL

-

FOUNDATION

-

PORCH

-

WINDOW MATERIAL

-

WINDOW MATERIAL 2

-

WINDOW TYPE

-

WINDOW CONFIGURATION

-

SIGNIFICANCE

-

HISTORIC FEATURES

-

ALTERATIONS

-

ADDITIONAL PHOTOGRAPHS



Photo Id: EChurch305

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

-

BUILDING MOVED?

-

MOVED FROM

-

ORIGINAL OWNER

Landmark Homes

ORIGINAL ARCHITECT

-

ARCHITECT SOURCE

-

BUILDER

Landmark Homes

SURVEYOR

LR

SURVEYOR ORGANIZATION

Ramsey Historic Consultants

SURVEY DATE

May-June 2016

SURVEY AREA

Downtown Libertyville

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

-

DATE OF CONSTRUCTION

-

PERMIT MOVING INFORMATION

MOVING PERMIT #

-

DATE MOVED

-

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

JRB-01-0056

DATE

03/20/2002

BUILDING PERMIT DESCRIPTION

Single family residence

COST

\$334, 080.00

ORIGINAL OWNER OCCUPIED?

No

EXTERIOR ALTERATION PERMITS

-

OTHER PERMIT INFORMATION

-

COA INFO

-

HISTORIC INFO

-

OTHER SOURCES

-

HISTORIC INFO COMPILER

LR

VOLUNTEER

-

Historic Libertyville

BEGINNING STREET NUMBER	<input type="text" value="313"/>
END STREET NUMBER	<input type="text" value="-"/>
STREET # SUFFIX	<input type="text" value="-"/>
STREET NAME	<input type="text" value="E. Church Street"/>
PIN	<input type="text"/>
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	<input type="text" value="No"/>
LOCAL DIST CONTRIB/NON-CONTRIB?	<input type="text" value="C"/>
LOCAL LANDMARK?	<input type="text" value="No"/>
YEAR	<input type="text" value="-"/>
LOCAL LANDMARK ELIGIBLE?	<input type="text" value="No"/>
CRITERIA	<input type="text" value="-"/>



Photo Id: ChurchStE313(1)

BUILDING DETAILS

BUILDING NAME	<input type="text" value="-"/>	ZONING	<input type="text" value="R-7"/>
GROUND FLOOR USE	<input type="text" value="Residence"/>	NUMBER OF STORIES	<input type="text" value="2"/>
UPPER FLOOR USE	<input type="text" value="Residential"/>	PROPERTY INDEX NUMBER	<input type="text" value="1116416002"/>
CURRENT OCCUPANT	<input type="text" value="-"/>		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	<input type="text" value="C"/>	NR ELIGIBLE?	<input type="text" value="No"/>
WITHIN DISTRICT?	<input type="text" value="No"/>	CRITERIA	<input type="text" value="-"/>
NR LANDMARK?	<input type="text" value="No"/>	ALTERNATE ADDRESS?	<input type="text" value="-"/>
YEAR	<input type="text" value="-"/>		

GENERAL INFORMATION

CATEGORY	<input type="text" value="Building"/>	HISTORIC USE	<input type="text" value="Domestic - single dwelling"/>
CONDITION	<input type="text" value="Good"/>	SECONDARY STRUCTURE	<input type="text" value="Detached garage"/>
INTEGRITY	<input type="text" value="Major alterations and additions"/>	NR SECOND	<input type="text" value="NC"/>
CURRENT USE	<input type="text" value="Domestic - single dwelling"/>		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

L-Form

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Assessor

WALL MATERIAL (CURRENT)

Aluminum/vinyl

WALL MATERIAL 2 (CURRENT)

-

PLAN

L

NO OF STORIES

1.5

ROOF TYPE

Multi-gable

ROOF MATERIAL

Asphalt - shingle

FOUNDATION

Not visible

PORCH

Front entry

WINDOW MATERIAL

Aluminum/vinyl

WINDOW MATERIAL 2

-

WINDOW TYPE

Double Hung

WINDOW CONFIGURATION

1/1

SIGNIFICANCE

-

HISTORIC FEATURES

L-shaped massing, with front-gable bay intersected by 1.5-story side gable bay; 1-story square window bay at east facade

ALTERATIONS

Replacement windows in original openings (2013); replacement siding (1991); replacement front porch (historic--1952); 2nd-story rear addition

ADDITIONAL PHOTOGRAPHS



Photo Id: ChurchStE313(4)



Photo Id: EEchurch313

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	<input type="text" value="520"/>
END STREET NUMBER	<input type="text" value="-"/>
STREET # SUFFIX	<input type="text" value="-"/>
STREET NAME	<input type="text" value="E. Church Street"/>
PIN	<input type="text"/>
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	<input type="text" value="No"/>
LOCAL DIST CONTRIB/NON-CONTRIB?	<input type="text" value="C"/>
LOCAL LANDMARK?	<input type="text" value="No"/>
YEAR	<input type="text" value="-"/>
LOCAL LANDMARK ELIGIBLE?	<input type="text" value="Yes"/>
CRITERIA	<input type="text" value="H"/>



Photo Id: ChurchStE520(1)

BUILDING DETAILS

BUILDING NAME	<input type="text" value="Earl Ladder Company/Fould's Milling Company"/>	ZONING	<input type="text" value="-"/>
GROUND FLOOR USE	<input type="text" value="Manufacturing"/>	NUMBER OF STORIES	<input type="text" value="Multiple"/>
UPPER FLOOR USE	<input type="text" value="Manufacturing"/>	PROPERTY INDEX NUMBER	<input type="text" value="-"/>
CURRENT OCCUPANT	<input type="text" value="Foulds Pasta Company"/>		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	<input type="text" value="C"/>	NR ELIGIBLE?	<input type="text" value="Yes"/>
WITHIN DISTRICT?	<input type="text" value="No"/>	CRITERIA	<input type="text" value="A"/>
NR LANDMARK?	<input type="text" value="No"/>	ALTERNATE ADDRESS?	<input type="text" value="-"/>
YEAR	<input type="text" value="-"/>		

GENERAL INFORMATION

CATEGORY	<input type="text" value="Building"/>	HISTORIC USE	<input type="text" value="Industry/Processing/Extraction - manufacturing facility"/>
CONDITION	<input type="text" value="Good"/>	SECONDARY STRUCTURE	<input type="text" value="-"/>
INTEGRITY	<input type="text" value="Moderate alterations and additions"/>	NR SECOND	<input type="text" value="-"/>
CURRENT USE	<input type="text" value="Industry/Processing/Extraction - manufacturing facility"/>		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Renaissance Revival

DETAILS

-

OTHER YEAR

additions--1906 (c); 1920 (c); 1955 (c)

DATE SOURCE

Illinois Digital Archives/Sanborn maps/surveyor

WALL MATERIAL (CURRENT)

Brick

WALL MATERIAL 2 (CURRENT)

Wood/concrete block

PLAN

Irregular

NO OF STORIES

3.5, 3, 2, 1

ROOF TYPE

Flat

ROOF MATERIAL

Not Visible

FOUNDATION

Not visible

PORCH

-

WINDOW MATERIAL

Wood

WINDOW MATERIAL 2

Aluminum/vinyl, Glass Block, Metal

WINDOW TYPE

Combination

WINDOW CONFIGURATION

Combination

SIGNIFICANCE

The Foulds Milling Company first began operation in this building (constructed for a ladder company in 1894) in 1905-6, and continues to manufacture pasta at this site. The building, which includes several historic additions dating from the early-to-mid 20th century, is eligible for designation as a local landmark and may also be eligible for individual listing to the National Register of Historic Places for its associations with Libertyville's industrial development and history.

HISTORIC FEATURES

3.5-story original section of building features stepped parapet with raised center bay; brick corbelling below parapet; paired round-arch window openings at 4th floor of front facade 3-story section east of original 3.5-story building is an historic addition dating from c. 1905-6--buff brick exterior matching original building, four slightly recessed bays across front facade, segmental arch window openings 2-story section east of 3-story c. 1905-6 addition dating from c. 1920 (Sanborn maps indicate that the building was originally 1-story, with 2nd story added some time between 1924 and 1933) Office addition at west end (late 1920s-early 1930s)

ALTERATIONS

[see historic features for historic additions] 2-story east end addition dating from c. 1955-60 Wood shed-roof and hipped-roof entry bays along south (front) facade; most windows on building either replacement (glass block, metal, and vinyl) in downsized openings or bricked in

ADDITIONAL PHOTOGRAPHS



Photo Id: ChurchStE520(2)



Photo Id: ChurchStE520(3)



Photo Id: FouldsFactory

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

From Illinois Digital Archives (information provided by Libertyville-Mundelein Historical Society and Cook Memorial Public Library District): "Factory and headquarters of Foulds Macaroni Company which moved to Libertyville from Cincinnati in 1906. The structure, originally a ladder factory, was built in 1894 with timbers from the 1893 World's Columbian Exposition in Chicago. In its early years Foulds was a major employer in Libertyville, well-known for its summer company picnics and winter Christmas parties to which the whole town was invited."

OTHER SOURCES

Historic photos of building at Illinois Digital Archives (in collection of Libertyville Mundelein Historical Society and Cook Memorial Public Library):
<http://www.idaillinois.org/cdm/singleitem/collection/cookmemo11/id/106/rec/3>
<http://www.idaillinois.org/cdm/singleitem/collection/cookmemo11/id/6167/rec/1>
<http://www.idaillinois.org/cdm/singleitem/collection/cookmemo11/id/2089/rec/2> Historic photo of building before additions (c. 1897) on p. 43 of LIBERTYVILLE ILLUSTRATED Sanborn Maps: 1907(Sheet 3), 1912 (Sheet 4), 1924 (Sheet 7), 1933 (Sheet 6), 1948 (Sheet 6)

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	107
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	W. Church Street
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	C
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ChurchStW107(1)

BUILDING DETAILS

BUILDING NAME	-	ZONING	C-1
GROUND FLOOR USE	Commercial	NUMBER OF STORIES	1
UPPER FLOOR USE	N/A	PROPERTY INDEX NUMBER	1116300100
CURRENT OCCUPANT	Craft Beer Store		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	C	NR ELIGIBLE?	No
WITHIN DISTRICT?	No	CRITERIA	-
NR LANDMARK?	No	ALTERNATE ADDRESS?	335 N. Milwaukee Avenue
YEAR	-		

GENERAL INFORMATION

CATEGORY	Building	HISTORIC USE	Commerce/Trade - business
CONDITION	Good	SECONDARY STRUCTURE	-
INTEGRITY	Minor alterations	NR SECOND	-
CURRENT USE	Vacant		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

One Part Commercial Block

DETAILS

-

OTHER YEAR

-

DATE SOURCE

Surveyor/Sanborn Map

WALL MATERIAL (CURRENT)

Brick

WALL MATERIAL 2 (CURRENT)

-

PLAN

Rectangular

NO OF STORIES

1

ROOF TYPE

Flat

ROOF MATERIAL

Not Visible

FOUNDATION

Not visible

PORCH

-

WINDOW MATERIAL

Metal

WINDOW MATERIAL 2

-

WINDOW TYPE

Storefront

WINDOW CONFIGURATION

-

SIGNIFICANCE

-

HISTORIC FEATURES

Rectangular massing; flat roof with stepped front brick parapet wall

ALTERATIONS

Storefront configuration altered (1949); awning (2008)

ADDITIONAL PHOTOGRAPHS



Photo Id: WChurch107



Photo Id: 107church

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

http://www.idaillinois.org/cdm/singleitem/collection/cookmemo11/id/2040/rec/40"/>

HISTORIC INFO COMPILER

VOLUNTEER

Historic Libertyville

BEGINNING STREET NUMBER	111-115
END STREET NUMBER	-
STREET # SUFFIX	-
STREET NAME	W. Church Street
PIN	
<u>LOCAL</u>	
WITHIN LOCAL DISTRICT?	No
LOCAL DIST CONTRIB/NON-CONTRIB?	NC
LOCAL LANDMARK?	No
YEAR	-
LOCAL LANDMARK ELIGIBLE?	No
CRITERIA	-



Photo Id: ChurchStW111-115(1)

BUILDING DETAILS

BUILDING NAME	-	ZONING	C-1
GROUND FLOOR USE	Commercial, Retail; Office	NUMBER OF STORIES	2
UPPER FLOOR USE	-	PROPERTY INDEX NUMBER	1116300099
CURRENT OCCUPANT	Enaz on The Park (111); Edward Jones (115)		

NATIONAL REGISTER

NR DISTRICT CONTRIB/NON-CONTRIB	NC	NR ELIGIBLE?	No
WITHIN DISTRICT?	No	CRITERIA	-
NR LANDMARK?	No	ALTERNATE ADDRESS?	-
YEAR	-		

GENERAL INFORMATION

CATEGORY	Building	HISTORIC USE	Commerce/Trade - business
CONDITION	Good	SECONDARY STRUCTURE	-
INTEGRITY	Major alterations and additions	NR SECOND	-
CURRENT USE	Commerce/Trade - business		

ARCHITECTURAL DESCRIPTION

ARCHITECTURAL CLASSIFICATION

Two Part Commercial Block (altered)

DETAILS

-

OTHER YEAR

1945 (c); 1952; later

DATE SOURCE

Surveyor; Sanborn Maps; Permit

WALL MATERIAL (CURRENT)

Brick

WALL MATERIAL 2 (CURRENT)

Concrete block

PLAN

Rectangular

NO OF STORIES

2

ROOF TYPE

Flat

ROOF MATERIAL

Not Visible

FOUNDATION

Not visible

PORCH

-

WINDOW MATERIAL

-

WINDOW MATERIAL 2

Aluminum/vinyl

WINDOW TYPE

Double hung & storefront

WINDOW CONFIGURATION

1/1; 1-light

SIGNIFICANCE

-

HISTORIC FEATURES

Building was originally a 1-story brick manufacturing structure built c. 1915-20; 1-story west side addition (c. 1945); second story addition (1952)

ALTERATIONS

More recent alterations include replacement windows, in upper and storefront levels, faux cornice with brackets; storefront signage; center entry and awning

ADDITIONAL PHOTOGRAPHS



Photo Id: WestChurch111-115



Photo Id: WestChurch111-115

HISTORIC INFORMATION

OLD ADDRESS (CITY DIR.YEAR)

BUILDING MOVED?

MOVED FROM

ORIGINAL OWNER

ORIGINAL ARCHITECT

ARCHITECT SOURCE

BUILDER

SURVEYOR

SURVEYOR ORGANIZATION

SURVEY DATE

SURVEY AREA

PERMIT/HISTORIC INFORMATION

OLD ADDRESS

DATE OF CONSTRUCTION

PERMIT MOVING INFORMATION

MOVING PERMIT #

DATE MOVED

ORIGINAL PERMIT INFORMATION

BUILDING PERMIT #

DATE

BUILDING PERMIT DESCRIPTION

COST

ORIGINAL OWNER OCCUPIED?

EXTERIOR ALTERATION PERMITS

OTHER PERMIT INFORMATION

COA INFO

HISTORIC INFO

OTHER SOURCES

HISTORIC INFO COMPILER

VOLUNTEER